

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/EP12/011185/Urf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) __ S + RS __ SI

) Photos

) Others

)

15/11/12 4/5 \$1200 confirmed with Alvin



友尼摩哆公司 UNIMOTOR COMPANY

一號加基武吉六道一樓門牌九十四號 新加坡郵區四一七八八三

AUTOBAY @ KAKI BUKIT

No. 1 KAKI BUKIT AVE 6 #01-94 SINGAPORE 417883

TELEPHONE: 6748 2795 FAX: 6747 2373

Registration No.: 203165/00D

LKK

DATE: 09/11/2021

OUR REF: UAPL1493

REPAIR ESTIMATE YOU THE HONDA STREAM NO: **SBP8878Z**

1 REAR BUMPER FACE	2el/1011	665.40	\$	1,185.00	✓
1 REAR L/H BUMPER RETAINER	11		\$	68.40	X
1 REAR L/H BUMPER SIDE SUPPORT HOLDER CLIPS	11		\$	22.50	X
6 REAR BUMPER CLIPS	11		\$	30.00	X
1 REAR L/H FENDER ASSY	R		\$	1,323.40	X
			\$	2,629.30	
			\$	525.86	
			\$	2,103.44	
LESS 20%.....					

SPECIAL NETT:-

1 REAR L/H SPORT WHEEL	11	\$	400.00	X
------------------------	----	----	--------	---

LABOUR CHARGES:-

TO SEND VEHICLE FOR COMPUTER ALIGHTMENT	11	\$	120.00	X
TO PANEL BEAT DAMAGED PORTION		\$	800.00	400
TO PUTTY AND RESPRAY DAMAGED PORTION		\$	800.00	400
TO SPRAY UNDERCOATING IN REPAIR		\$	80.00	X
TO DISM/REFIX REAR L/H FENDER GLASS IN REPAIR	11	\$	140.00	X
TO DISM/REFIX REAR SEAT, TRAY ASSY, PILLER LINING, ROOF LINING		\$	100.00	80
		\$	4,543.44	

not Authorised
2/5 \$1200
10/11/21
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 695.40
202
P- 556.32
L- 960.00
15-16/32
202
1213