

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011187/EGA3Q2**Date:** 30/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02
Claimant Vehicle No : SMX4123Y **Insured Vehicle No :** GBL1932S
 Date of Loss: 28/10/2021 Nature of Claim: TP Claim No: MFL2021D0004803

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMX4123Y**
 Make & Model: KIA CERATO, 1.6 LX (A) Engine No: G4FGKH756711
 Reg. Date: 12/01/2021 (Man. Year: 2019) Chassis No: KNAF1416ML5070285
 Colour: Grey Odometer: 11760 km
 Engine Capacity: 1591 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Kumho 5 mm Rear Left Side: Kumho 5 mm
 Front Right Side: Kumho 5 mm Rear Right Side: Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,568.00	10,179.00	389.00	3.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,540.00	13,540.00	1,000.00	6.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	25,108.00	23,719.00	1,389.00	5.53
+ GST 7.00/7.00% (S\$)	1,757.56	1,660.33	97.23	5.53
Nett Amount (S\$)	26,865.56	25,379.33	1,486.23	5.53
+ Car Rental (26.0 x S\$100.00/day + 7.00% GST) (S\$)		2,782.00		
	Nett Liability (S\$)	28,161.33		

INSPECTION

Date of Assignment: 01/11/2021
 Date Inspected: 02/11/2021 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
 209 Pandan Gardens
 Singapore 609339
 Estimated Period of Repair: 20.0 days

Adjuster: CHEN TSUE YEE**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jan 2022)
Parts: 143	KIA CERATO 1.6 LX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMX4123Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Broken	651.00 FS	*651.00 FS
2	1		*COVER -RR BUMPER LWR	Broken	241.00 FS	*241.00 FS
3	1		*COVER-RR BUMPER UNDER ,LH	Crushed	33.00 FS	*33.00 FS
4	1		*COVER-RR BUMPER FOG LAMP ,LH	Broken	19.00 FS	*19.00 FS
5	1		*COVER-RR BUMPER FOG LAMP ,RH	Cut	19.00 FS	*19.00 FS
6	1		*LAMP ASSY- SIDE T/SIGNAL LH	Broken	181.00 FS	*181.00 FS
7	1		*LAMP ASSY- SIDE T/SIGNAL RH	Not Necessary	181.00 FS	*- FS
8	1		*EXTN WIRING ASSY -BWS	Torn	207.00 FS	*207.00 FS
9	1		*BEAM -RR BUMPER	Broken	318.00 FS	*318.00 FS
10	1		*STAY -RR BUMPER LH	Dented	65.00 FS	*65.00 FS
11	1		*STAY -RR BUMPER RH	Dented	65.00 FS	*65.00 FS
12	1		*BRACKET -RR BEAM UPR MTG ,LH	Broken	9.00 FS	*9.00 FS
13	1		*BRACKET -RR BEAM UPR MTG ,RH	Broken	9.00 FS	*9.00 FS
14	1		*BRACKET-RR BEAM LWR ,CTR	Broken	6.00 FS	*6.00 FS
15	1		*BRACKET-RR BEAM LWR ,MTG	Broken	6.00 FS	*6.00 FS
16	1		*COVER -RR BUMPER UNDER ,RH	Not Necessary	33.00 FS	*- FS
17	1		*BRACKET ASSY -RR BPR SIDE UPR ,L	Broken	25.00 FS	*25.00 FS
18	1		*BRACKET ASSY -RR BPR SIDE UPR ,R	Broken	31.00 FS	*31.00 FS
19	1		*NEW K3 2020 STEEL GRAY KLG	Dented	1,721.00 FS	*1,721.00 FS
20	1		*PANEL ASSY -BACK	Dented	324.00 FS	*324.00 FS
21	1		*TRIM ASSY -RR TRANSVERSE	Broken	41.00 FS	*41.00 FS
22	1		*PANEL ASSY -TRUNK LID	Dented	1,297.00 FS	*1,297.00 FS
23	1		*HINGE ASSY -TRUNK LID ,LH	Bent	97.00 FS	*97.00 FS
24	1		*HINGE ASSY -TRUNK LID ,RH	Bent	97.00 FS	*97.00 FS
25	1		*W/STRIP -TRUNK LID OPNG	Crushed	100.00 FS	*100.00 FS
26	1		*LATCH ASSY -TRUNK LID	Bent	112.00 FS	*112.00 FS
27	1		*STRIKER ASSY -TRUNK LID	Not Necessary	40.00 FS	*- FS
28	1		*TRIM ASSY -TRUNK LID	Crushed	202.00 FS	*202.00 FS
29	1		*LOGO ASSY -KIA SUB	Necessary	32.00 FS	*32.00 FS
30	1		*EMBLEM -CERATO	Necessary	28.00 FS	*28.00 FS
31	1		*LAMP ASSY -CENTER GARNISH	Broken	638.00 FS	*638.00 FS
32	1		*LAMP ASSY -REAR COMB INSIDE ,LH	Broken	242.00 FS	*242.00 FS
33	1		*LAMP ASSY -REAR COMB INSIDE ,RH	Broken	242.00 FS	*242.00 FS
34	1		*LAMP ASSY -REAR COMB OUTSIDE ,LH	Broken	274.00 FS	*274.00 FS
35	1		*LAMP ASSY -REAR COMB OUTSIDE ,RH	Broken	274.00 FS	*274.00 FS
36	1		*PANEL ASSY -QAURTER OUTER ,LH	Dented	1,349.00 FS	*1,349.00 FS
37	1		*PANEL ASSY -RR COMB LAMP HSG ,LH	Bent	139.00 FS	*139.00 FS
38	1		*PANEL ASSY -RR COMB LAMP HSG ,RH	Repair	135.00 FS	*- FS
39	10		*PAD-WINDSHIELD GLASS	Necessary	20.00 FS	*20.00 FS
40	2		*STOPPER -GLASS	Necessary	8.00 FS	*8.00 FS
41	1		*BRACKET ASSY -SPARE TIRE MTG	Necessary	15.00 FS	*15.00 FS
42	1		*PANEL ASSY -REAR FLOOR ,RR	Necessary	219.00 FS	*219.00 FS
43	1		*REINF ,RR SPARE TIRE WELL CROSS	Necessary	41.00 FS	*41.00 FS
44	1		*REINF-TOWING HOOK	Necessary	14.00 FS	*14.00 FS
45	1		*HOOK -TOWING	Necessary	16.00 FS	*16.00 FS
46	1		*TRIM ASSY -LUGGAGE SIDE RH	Crushed	200.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TRIM ASSY -LUGGAGE SIDE LH	Crushed	200.00 FS	*200.00 FS
48	1		*FASTENER	Necessary	1.00 FS	*1.00 FS
49	10		*CLIP	Necessary	20.00 FS	*20.00 FS
50	1		*KEY SUB SET -TRUNK	Bent	78.00 FS	*78.00 FS
51	1		*TERMICAL -RR WDO GLASS DEFOGGER	Necessary	4.00 FS	*4.00 FS
52	1		*SILENCER ,FLOOR	Necessary	13.00 FS	*13.00 FS
53	1		*PROTECTOR -HEAT REAR	Bent	136.00 FS	*136.00 FS
54	1		*INSULATOR	Necessary	70.00 FS	*70.00 FS
55	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
Total Parts (S\$)					10,568.00	10,179.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	110.00	110.00
2	REPLACE REAR FLOOR PANEL ,REPAIR BOTH CHASSIS FRAME ,SPEAKER PANEL	New	1,600.00	1,600.00
3	RESPRAY ON SPEAKER PANEL & REAR FLOOR PANEL	New	1,100.00	1,100.00
4	RENEW RR BUMPER ,RR BUMPER BODY KIT ,RR END PNL ,BOOTLID & LHR FENDER REPAIR RHR FENDER	New	4,560.00	4,560.00
5	RESRPAY RR BUMPER ,RR BUMPER BODY KIT ,RR END PNL,BOOTLID ,BOOTLID SPOILER ,LHR FENDER & RHR FENDER	New	3,850.00	3,850.00
6	REMOVE & REFIT BOOTLID COMPONENT	New	300.00	300.00
7	REMOVE & REFIT FUEL TANK ASSY	New	320.00	320.00
8	REMOVE & REFIT RR FLR BOARD ,TRIM ,CARPET & SEAT TO GIVE WAY FOR REPAIR	New	300.00	300.00
9	CHECK WIRING ELECTRICAL SYSTEM	New	80.00	80.00
10	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM	New	300.00	300.00
11	CONDUCT CHASSIS ALIGNMENT -CELETTE BENCH	New	1,000.00	0.00
12	REMOVE & REFIT RR WINDSCREEN GLASS	New	300.00	300.00
13	SUPPLY WINDSCREEN SEALANT	New	80.00	80.00
14	SUPPLY RR BUMPER PLATE WITH CASING	New	80.00	80.00
15	RESEAL RR NUMBER PLATE	New	120.00	120.00
16	REMOVE & REFIT REVERSE SENSOR	New	50.00	50.00
17	SUPPLY REVERSE SENSOR	New	220.00	220.00
18	APPLY ANTI CORROSION ON AFFECTED AREAS	New	40.00	40.00
19	SUPPLY BODY PNL SEALANT	New	80.00	80.00
20	SUPPLY C&C BADGE	New	50.00	50.00
Gross Labour Cost (\$\$)			14,540.00	13,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >