

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011188/KGA3Q2**Date:** 02/06/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SHD9978D **Insured Vehicle No :** SLT695Y
 Date of Loss: 31/10/2021 Nature of Claim: TP Claim No: MFL2021D0004770

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD9978D**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR2G76320
 Reg. Date: 03/08/2020 (Man. Year: 2020) Chassis No: JTDKB3FU003091252
 Colour: Metallic Pearl White/Red Odometer: 258075 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Sailun 8 mm Rear Left Side: Sailun 7 mm
 Front Right Side: Sailun 8 mm Rear Right Side: Sailun 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,040.72	695.07	2,345.65	77.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,500.00	480.00	5,020.00	91.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,540.72	1,175.07	7,365.65	86.24
+ GST 7.00/7.00% (S\$)	597.85	82.25	515.60	86.24
Nett Amount (S\$)	9,138.57	1,257.32	7,881.25	86.24
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$112.35/day) (S\$)		337.05		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		1,751.82		
Global Sum Settlement (S\$)		1,750.00		

INSPECTION

Date of Assignment: 02/11/2021
 Date Inspected: 02/11/2021 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 1.5 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 May 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD9978D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,REAR BUMPER	Bent	485.60 FL	*485.60 FL
2	1		*REINFORCEMENT SUB-ASSY ,REAR BUMPER	Repair	332.70 FL	*- FL
3	1		*GUARD ,REAR BUMPER CENTER	Damaged	374.50 FL	*374.50 FL
4	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	118.30 FL	*- FL
5	1		*RETAINER ,REAR BUMPER SIDE ,RH	Serviceable	132.60 FL	*- FL
6	1		*REFLECTOR ASSY ,REFLEX RH	Serviceable	39.00 FL	*- FL
7	1		*LENS & BODY REAR COMBINATION LAMP , RH	Serviceable	339.60 FL	*- FL
8	1		*LENS & BODY REAR COMBINATION LAMP ,NO.2 RH	Serviceable	261.00 FL	*- FL
9	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Repair	651.00 FL	*- FL
10	1		*REAR BUMPER SIDE CLIP	Necessary	60.00 FS	*50.00 FS
11	1		*TAIL LAMP CLIP	Not Necessary	70.00 FS	*- FS
12	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
13	1		*SET REAR BUMPER CLIP	Not Necessary	85.00 FS	*- FS
14	1		*REAR BUMPER RETAINER CLIP	Not Necessary	75.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,724.30	910.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	683.58	215.03
Total Parts (\$\$)	3,040.72	695.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING AND APPLT UNDERCOAT OF THE AFFECTED AREAS	New	240.00	0.00
2	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
3	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	2,000.00	200.00
4	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
5	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,600.00	220.00
6	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
8	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
9	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
10	TO REMOVE AND REFIT OF REAR FENDER FITTINGS ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
Gross Labour Cost (\$\$)			5,500.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >