

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG21011190/UQF3Q2
Date: 16/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900018235
Claimant Vehicle No :	SKU46C	Insured Vehicle No :	SMH9464P
Date of Loss:	29/10/2021	Nature of Claim:	TP
		Claim No:	7601190058SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU46C		
Make & Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Engine No:	27091030690304
Reg. Date:	02/07/2015 (Man. Year: 2015)	Chassis No:	WDD1760422J382449
Colour:	Silver	Odometer:	95645 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021

Estimated Period of Repair: 3.0 days

Inspected At:

Garage 13 Pte Ltd (HQ)
8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Singapore 415875

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$58,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	0.00 F	*- F
2	1		*REAR BUMPER DIFFUSER	Deformed	0.00 F	*- F
3	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER BEAM	Dented	0.00 F	*- F
5	2		*REAR BUMPER PDC SENSOR	Shorted	0.00 F	*- F
6	1		*REAR END PANEL	Repair	0.00 F	*- F
7	1		*REAR EXHAUST HEAT SHIELD	Repair	0.00 F	*- F
					Total Parts (S\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >