

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG21011192/T1VF3Q2
Date: 10/11/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800022340
Claimant Vehicle No :	PC3418D	Insured Vehicle No :	SLW8303K
Date of Loss:	16/10/2021	Nature of Claim:	TP
		Claim No:	5708943770SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC3418D	Engine No:	1KD2437904
Make & Model:	MITSUBISHI CANTER, 3.0 D (A)	Chassis No:	JTFST22P700021148
Reg. Date:	24/11/2014 (Man. Year: 2014)	Odometer:	251263 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/11/2021

Date Inspected: 02/11/2021 Inspected At:

1 Stop Garage Pte Ltd - (Serangoon North) (HQ)
55 SERANGOON NORTH AVENUE 4, #02-10 S9 BUILDING
Singapore 555859

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$32,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Necessary	0.00 F	*- F
4	4		*REAR BUMPER LOWER BRACKET	Bent	0.00 F	*- F
5	1		*REVERSE SENSOR	Not Working	0.00 F	*- F
6	1		*REAR END PANEL	Bent	0.00 F	*- F
7	1		*REAR END PANEL TOP GARNISH	*Check	0.00 F	*- F
8	1		*TAILGATE	Bent	0.00 F	*- F
9	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
10	1		*TAILGATE LOCK	Bent	0.00 F	*- F
11	1		*TAILGATE RUBBER	Cut	0.00 F	*- F
12	1		*TAILGATE INNER BOARD	*Check	0.00 F	*- F
13	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
14	1		*STICKER	Necessary	0.00 F	*- F
15	1		*SPATE TYRE BRACKET	Bent	0.00 F	*- F
16	1		*SPATE TYRE BRACKET SCRAW	Bent	0.00 F	*- F
F=Franchise part.						
					Total Parts (S\$)	0.00
						0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >