

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011193/APA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant Vehicle No : SLH1261Y **Insured Vehicle No :** SLN2389A
 Date of Loss: 30/10/2021 Nature of Claim: TP Claim No: 1565884033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLH1261Y**
 Make & Model: HONDA VEZEL, 1.5 G (A) Engine No: L15Z1000871
 Reg. Date: 08/10/2021 (Man. Year: 2021) Chassis No: RV31000687
 Colour: Red Odometer: 1127 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,964.16	12,156.24	8,807.92	42.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	2,490.00	1,610.00	39.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,064.16	14,646.24	10,417.92	41.57
Approved Total (Overridden) (S\$)		11,700.00		
Nett Amount (S\$)	25,064.16	11,700.00	13,364.16	53.32
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		12,436.45		
Global Sum Settlement (S\$)		12,400.00		

INSPECTION

Date of Assignment: 02/11/2021
 Date Inspected: 02/11/2021 Inspected At: JL Perfect Autowork Pte Ltd (HQ)
 8 Kaki Bukit Avenue 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (LOWER)	Cut	439.10 FL	*439.10 FL
2	1		*FRONT BUMPER (UPPER)	Distorted	927.50 FL	*927.50 FL
3	1		*FRONT BUMPER LOWER DIFFUSER	Cut	381.70 FL	*381.70 FL
4	1		*FRONT BUMPER SENSOR WIRE HARNESS	Cut	532.60 FL	*532.60 FL
5	1		*FRONT BUMPER SENSOR (4 PCS)	Damaged (1 PCS ONLY)	506.80 FL	*126.70 FL
6	4		*FRONT BUMPER SENSOR HOLDER	Necessary (2 PCS ONLY)	101.20 FL	*50.60 FL
7	1		*FRONT BUMPER FOGLAMP	N/S Cut	1,021.40 FL	*510.70 FL
8	1		*FRONT BUMPER FOGLAMP COVER	N/S Cut	120.40 FL	*60.20 FL
9	1		*FRONT BUMPER LOWER GRILLE	Deformed	150.20 FL	*150.20 FL
10	1		*FRONT BUMPER SIDE RETAINER	N/S Cracked	46.00 FL	*23.00 FL
11	2		*FRONT BUMPER REINFORCEMENT TOP GARNISH	Not Necessary	190.00 FL	*- FL
12	1		*FRONT BUMPER REINFORCEMENT	Dented	386.90 FL	*386.90 FL
13	1		*FRONT BUMPER TOWING COVER	Not Necessary	65.30 FL	*- FL
14	1		*FRONT FENDER	N/S Distorted / O/S Repair	1,160.00 FL	*580.00 FL
15	2		*FRONT FENDER COWLING	Not Necessary	292.00 FL	*- FL
16	2		*FRONT FENDER ARCD GARNISH	Deformed	391.60 FL	*391.60 FL
17	1		*FRONT WHEEL HOUSE SUPPORT PANEL LH	Repair	263.00 FL	*- FL
18	1		*FRONT WHEEL HOUSE EXTEND PANEL LH	Repair	163.00 FL	*- FL
19	1		*CENTER GRILLE TOP COVER	Deformed	169.00 FL	*169.00 FL
20	1		*CENTER GRILLE LOGO	Necessary	39.00 FL	*39.00 FL
21	1		*CENTER GRILLE BASE	Cracked	463.00 FL	*463.00 FL
22	1		*CENTER GRILLE OUTER MOULDING	Cracked	368.00 FL	*368.00 FL
23	1		*CENTER GRILLE UPPER MOULDING	Not Necessary	84.00 FL	*- FL
24	2		*CENTER GRILLE LOWER MOULDING	Cracked	168.00 FL	*168.00 FL
25	1		*CENTER GRILLE CHROME MOULDING	Cracked	138.00 FL	*138.00 FL
26	1		*CENTRE GRILLE SUPPORT BRACKET	Not Necessary	217.00 FL	*- FL
27	1		*HEADLAMP (LED)	N/S Cracked	7,358.00 FL	*3,200.00 FL
28	1		*HEADLAMP LOWER BRACKET	N/S Cracked	134.00 FL	*67.00 FL
29	1		*BONNET	Distorted	1,326.00 FL	*1,180.00 FL
30	1		*BONNET LOCK	Not Necessary	178.00 FL	*- FL
31	2		*BONNET INNER RUBBER (FRONT)	Not Necessary	54.00 FL	*- FL
32	2		*BONNET INNER RUBBER (SIDE)	Not Necessary	58.00 FL	*- FL
33	1		*BONNET INSULATOR	Crumpled	274.00 FL	*274.00 FL
34	2		*BONNET STOPPER	Not Necessary	39.00 FL	*- FL
35	1		*BONNET HINGE	N/S Bent	90.00 FL	*45.00 FL
36	1		*FRONT SUPPORT PANEL	Dented	796.00 FL	*796.00 FL
37	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	185.00 FL	*- FL
38	1		*RADIATOR	Dented	1,365.00 FL	*1,365.00 FL
39	1		*RADIATOR SIDE GARNISH	N/S Cracked	136.00 FL	*68.00 FL
40	4		*RADIATOR RUBBER MOUNTING	Not Necessary	112.00 FL	*- FL
41	1		*RADIATOR FAN COWLING	Cracked	175.00 FL	*175.00 FL
42	2		*RADIATOR BRACKET	Not Necessary	128.00 FL	*- FL
43	1		*AIR CON CONDENSER	Bent	1,160.00 FL	*1,160.00 FL
44	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	112.00 FL	*- FL
45	1		*AIR CON FAN COWLING	Not Necessary	168.00 FL	*- FL
46	2		*AIR CON CONDENSER BRACKET	Not Necessary	70.00 FL	*- FL
47	1		*AIR DUCT	Not Necessary	142.00 FL	*- FL
48	1		*AIR FLEXIBLE DUCT	Not Necessary	165.00 FL	*- FL
49	1		*AIR CLEANER RESONATOR BOX	Cracked	387.00 FL	*387.00 FL
50	1		*AIR CLEANER RESONATOR DUCT	Not Necessary	139.00 FL	*- FL
51	1		*FRONT TEMPERATURE SENSOR	Not Necessary	142.00 FL	*- FL
52	1		*HORN	Not Necessary	105.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
53	1		*BATTERY TRAY	Not Necessary	38.00 FL	*- FL	
54	1		*BATTERY BRACKET	Not Necessary	68.00 FL	*- FL	
55	1		*BATTERY BASE PANEL	Not Necessary	87.00 FL	*- FL	
56	1		*FRONT FUSE BOX LH	Not Necessary	865.00 FL	*- FL	
57	1		*FRONT TEMPERATURE SENSOR	Not Necessary	142.00 FL	*- FL	
58	1		*FRONT NUMBER PLATE	Dented	50.00 FS	*50.00 FS	
59	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS	
60	1		*SET FRONT BUMPER REINFORCEMENT TOP GARNISH CLIP	Not Necessary	30.00 FS	*- FS	
61	1		*SET FRONT FENDER ARCD GARNISH CLIP	Necessary	50.00 FS	*30.00 FS	
62	1		*SET CENTRE GRILLE CLIP	Necessary	30.00 FS	*20.00 FS	
63	1		*SET ENGINE UNDER CENTER COVER CLIP	Not Necessary	30.00 FS	*- FS	
64	1		*BONNET SEALANT	Not Necessary	80.00 FS	*- FS	
65	1		*SET BONNET INSULATOR CLIP	Necessary	50.00 FS	*30.00 FS	
66	1		*FRONT WHEEL HOUSE SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
67	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	80.00 FS	*- FS	
68	1		*SET FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	50.00 FS	*- FS	
69	1		*SET RADIATOR SIDE GARNISH LH	Necessary	30.00 FS	*10.00 FS	
70	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS	
71	1		*SET FRONT FENDER ARCED GARNISH CLIP	Necessary	50.00 FS	*20.00 FS	
72	1		*COOLANT	Necessary	40.00 FS	*40.00 FS	
73	1		*RELAY BOX	Cracked	285.00 FL	*285.00 FL	
					Sub Total (S\$)	26,017.70	15,137.80
					- List Item Discount on L Items 20.00/20.00% (S\$)	5,053.54	2,981.56
					Total Parts (S\$)	20,964.16	12,156.24

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	1,800.00	1,000.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,600.00	1,200.00
3	REMOVE AND REFIX WINDSCREEN AND WIRING CHECKING	New	180.00	120.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
7	REFOCUS HEADLAMP BEAM	New	60.00	0.00
8	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
			Gross Labour Cost (\$\$)	4,100.00
				2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >