

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 9736A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	DISTORTED	815.60	815.60
1	REAR BUMPER REINFORCEMENT (CONSISTENT)	BENT	458.40	254.00
2	REAR BUMPER SIDE RETAINER @\$96.10(CONSISTENT)	DAMAGED	192.20	90.00
1	REAR BUMPER CENTER BEAM (CONSISTENT)	BENT	198.20	198.20
2	REAR BUMPER REFLECTOR @\$95.60(CONSISTENT)	CRACKED	191.20	191.20
1	REAR BUMPER TOW COVER (CONSISTENT)	DEFORMED	55.60	55.60
2	REAR BUMPER NUMBER PLATE LAMP @\$99.30 (CONSISTENT)	CRACKED	198.60	198.60
2	REAR BUMPER NUMBER PLATE LAMP BRACKET @ \$43.60(CONSISTENT)	BENT	87.20	87.20
1	REAR BUMPER NUMBER PLATE WIRE HARNESS (CONSISTENT)	NOT NECESSARY	321.20	-
1	REAR BOOTLID (CONSISTENT)	BUCKLED	693.10	693.10
1	REAR BOOTLID LOCK (CONSISTENT)	DAMAGED	298.60	155.00
1	REAR BOOTLID LOCK CATCH (CONSISTENT)	NOT NECESSARY	143.60	-
1	REAR BOOTLID LOCK DETECTOR (CONSISTENT)	CRACKED	165.40	165.40
1	REAR BOOTLID INNER TRIM BOARD (CONSISTENT)	NOT NECESSARY	298.70	-
2	REAR BOOTLID HINGE @\$98.10(CONSISTENT)	NOT NECESSARY	196.20	-
2	REAR BOOTLID SHOCK ABSORBER @\$328.40 (CONSISTENT)	NOT NECESSARY	656.80	-
2	REAR BOOTLID LAMP @\$389.40(CONSISTENT)	CUT	778.80	642.00
1	REAR BOOTLID EMBLEM LOGO(CONSISTENT)	NECESSARY	55.60	55.60
1	REAR BOOTLID THIRD BRAKE LAMP (CONSISTENT)	NOT NECESSARY	165.30	-
1	REAR WEATHERSTRIPE(CONSISTENT)	CUT	214.50	214.50
1	REAR END PANEL (CONSISTENT)	DENTED	589.10	589.10
1	REAR END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	235.60	144.00
2	REAR FENDER INNER TRIM @\$497.60(CONSISTENT)	TORN	995.20	446.00
1	REAR SPARE TYRE COMPARTMENT PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	954.30	-
1	REAR SPARE TYRE TOP BOARD (CONSISTENT)	TORN	447.30	158.00
1	REAR EXHAUST MUFFLER (CONSISTENT)	NOT NECESSARY	983.60	-
1	REAR EXHAUST MUFFLER SHIELD (CONSISTENT)	NOT NECESSARY	124.60	-

Report Ref No. CC4/ASM21011195/Aps3q2



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
2	REAR EXHAUST MUFFLER RUBBER MOUNTING @\$42.30 (CONSISTENT)	NOT NECESSARY	84.60	-
2	REAR TAILLAMP @\$489.20(CONSISTENT)	CUT	978.40	712.00
2	REAR TAILLAMP LOWER BRACKET @\$86.40 (CONSISTENT)	NOT NECESSARY	172.80	-
1	REAR KEYLESS SENSOR (CONSISTENT)	REPEATED	288.40	-
1	REAR KEYLESS BUZZER (CONSISTENT)	REPEATED	213.20	-
	LESS 10% DISCOUNT		-1,225.19	-586.51
			11,026.71	5,278.59
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	80.00	30.00
2	REAR TAILLAMP CLIPS @\$12.00 (SN)(CONSISTENT)	NECESSARY	24.00	24.00
1	REAR END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	10.00
1	REAR END PANEL SEALANT (SN)(CONSISTENT)	NECESSARY	80.00	60.00
1	REAR NUMBER PLATE WITH CASING (SN)(CONSISTENT)	DENTED	60.00	50.00
1	REAR BUMPER REVERSE SENSOR (SN)(CONSISTENT)	DAMAGED	250.00	200.00
			554.00	374.00
	<u>LABOUR</u>			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR SPARE TYRE COMPARTMENT PANEL .		1,800.00	1,000.00
	LABOUR FOR SPRAYPAINTING.		1,400.00	1,000.00
	WIRING CHECK.		80.00	30.00
	LABOUR FOR REMOVE & TRANSFER ALL REAR BOOTLID FITTING.		200.00	80.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS .		300.00	60.00
	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE .	NOT NECESSARY	250.00	-
	LABOUR TO REMOVE REVERSE SENSOR .		100.00	50.00
			4,130.00	2,220.00
	GRAND TOTAL		15,710.71	7,872.59



Page No.:3 of 3

RECOMMENDED COST OF LUMP SUM REPAIRS		6,300.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CC4/ASM21011195/Aps3q2



**Chew Hsiao Tong**