



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                         |  |  |  |                |
|---|--|--|--|----------------|
| AXA INSURANCE PTE LTD<br>8 SHENTON WAY #24-01<br>AXA TOWERSINGAPORE 068811<br>ATTN:YVONNE |  |  | Ref: CC4/ASM21011195/Aps3q2<br>Date: 23/12/2021<br>Code: ASM |                |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>   |  |  |  |                |
|   | <b>Insured Veh.</b>  | SHC 1659H  | <b>Veh. Inspected</b>  | SJK 9736A      |
|   | <b>Policy No.</b>  | P2419138   | <b>Coverage (\$)</b>   | 0.00           |
|   | <b>Claim No.</b>   | S1M03L7V   | <b>Excess (\$)</b>   | 0.00           |
|   | <b>Assign From</b>   |  | <b>Assign Date</b>   | 02/11/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |  |  |                |
|   | <b>Make &amp; Model</b>  | mitsubishi LANCER  | <b>c.c</b>   | 1499           |
|   | <b>Engine No.</b>  | HIDDEN   | <b>Year of Reg.</b>  | 2008           |
|   | <b>Chassis No.</b>   | JMYSRCY2A9U001782  | <b>Colour</b>  | BLACK          |
|   | <b>Odometer</b>  | 198780 KM  | <b>Steering</b>  | IN ORDER       |
|   | <b>Brakes</b>  | IN ORDER   | <b>Modification</b>  | SPORTS RIM     |
|   | <b>General</b>   | GOOD   |  |                |
| <b>3. Conditions of Tyres</b>   |  |  |  |                |
|   |  | <b>Size</b>  | <b>Make</b>  | <b>Balance</b> |
|   | <b>R/H Front Tyre</b>  | 225/45 R17   | BRIDGESTONE  | 6 mm           |
|   | <b>L/H Front Tyre</b>  | 225/45 R17   | BRIDGESTONE  | 6 mm           |
|   | <b>R/H Rear Tyre</b>   | 225/45 R17   | BRIDGESTONE  | 6 mm           |
|   | <b>L/H Rear Tyre</b>   | 225/45 R17   | BRIDGESTONE  | 6 mm           |
| <b>4. Description of Damages</b>  |  |  |  |                |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br><br>DAMAGES SEE DETAILS.   |  |  |                |
| <b>5. General Information</b>   |  |  |  |                |
|   | <b>Accident Date</b>   | 01/11/2021   | <b>Inspection Date</b>                                       | 02/11/2021     |
|   | <b>Survey held at</b>  | NEW HOCK TECK MOTOR PTE LTD<br>1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |  |                |
| <b>5a. Remarks</b>  |  |  |  |                |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |  |                |
| <b>5b. Estimate Days of Repair</b>  |  |  |  |                |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |  | <b>6 Working Days</b>  |                |