

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011214/EPA3Q2**Date:** 18/06/2023**REFERENCE**

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0001405_02
Claimant Vehicle No : SKS4370A **Insured Vehicle No :** SJP2134G
 Date of Loss: 26/10/2021 Nature of Claim: TP Claim No: MPC2021D0004690

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKS4370A**
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520273352
 Reg. Date: 15/04/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0307573
 Colour: Grey Odometer: 52786 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Yokohama 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Yokohama 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,730.50	1,522.40	5,208.10	77.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,050.00	4,100.00	2,950.00	41.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,780.50	5,622.40	8,158.10	59.20
+ GST 7.00/7.00% (S\$)	964.64	393.57	571.07	59.20
Nett Amount (S\$)	14,745.14	6,015.97	8,729.17	59.20
+ Loss of Use (5.0 x S\$70.00/day) (S\$)		350.00		
Nett Liability (S\$)		6,365.97		

INSPECTION

Date of Assignment: 02/11/2021
 Date Inspected: 03/11/2021 Inspected At: Trans Eurokars Pte Ltd - Tanjong Penjuru (HQ)
 27A Tanjong Penjuru
 Singapore 609042
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Sep 2022)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS4370A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Crushed	1,083.30 F	*1,083.30 F
2	1		*RETAINER RH FRT	Necessary	19.70 F	*19.70 F
3	10		*NUT CLIP	Necessary	37.00 F	*37.00 F
4	2		*FASTENER	Necessary	6.00 F	*6.00 F
5	2		*GROMMET SCREW	Necessary	5.80 F	*5.80 F
6	1		*FRONT FENDER RH	Dented	350.60 F	*350.60 F
7	1		*STAY FENDER RH FRT	Not Necessary	37.40 F	*- F
8	1		*MUD GUARD RH FRT	Not Necessary	101.90 F	*- F
9	10		*FASTENER	Not Necessary	30.00 F	*- F
10	1		*WHEEL DISC 16X6.5 ALUM	Not Necessary	1,156.80 F	*- F
11	1		*VALVE AIR TYRE	Not Necessary	6.70 F	*- F
12	1		*FRONT ABSORBER RH	Not Necessary	360.80 F	*- F
13	1		*BEARING TOP FRT ABSORBER RH	Not Necessary	55.80 F	*- F
14	1		*RUBBER MOUNTING ABSORBER FRT RH	Not Necessary	96.50 F	*- F
15	1		*KNUCKLE FRT RH	Not Necessary	402.60 F	*- F
16	1		*HUB WHEEL BEARING FRT RH	Not Necessary	568.80 F	*- F
17	1		*HEADLAMP RH	Not Necessary	2,357.30 F	*- F
18	1		*FASTENER	Not Necessary	3.50 F	*- F
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					6,730.50	1,522.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER ,FRONT FENDER RH AND REPAIR FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS	New	2,640.00	1,320.00
2	TO RESPRAY FRONT BUMPER ,FRONT FENDER RH AND FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS	New	2,520.00	1,890.00
3	TO REPLACE AXLE AND SUSPENSION MECHANISM	New	660.00	0.00
4	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT	New	560.00	560.00
5	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING	New	120.00	0.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONINGS	New	250.00	150.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	300.00	180.00
Gross Labour Cost (\$)			7,050.00	4,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >