



**TRANS EUROKARS PTE LTD**  
27A TANJONG PENJURU, SINGAPORE 609042  
**ESTIMATE COST OF REPAIRS**



<b>INDIA INTERNATIONAL INSURANCE P/L</b> 64 CECIL STREET #04-#05 IOB BUILDING SINGAPORE 049711 <b>ATTN. :</b> MOTOR CLAIMS <b>FAX :</b>		<b>NAME :</b> <b>ADDRESS :</b> <b>TEL :</b>		<b>WIP :</b> 43037 <b>EXCESS :</b> <b>DATE :</b> 27-Oct-21	
<b>VEH NO :</b>	SKS4370A	<b>DATE IN :</b>		<b>CONTACT PERSON :</b>	JESS
<b>CHASSIS NO :</b>	JM6BM42A8G0307573	<b>MILEAGE :</b>		<b>TYPE OF CLAIM :</b>	THIRD PARTY CLAIM
<b>MODEL :</b>	MAZDA 3	<b>DATE REG.</b>	15-Apr-15	<b>POLICY NO. :</b>	

NATURE OF WORKS									
NO	DESCRIPTION	QTY	Unit Price	Disc %	1st	Supp	PARTS NO	REVISED	PRICES
1	FRONT BUMPER	1	1,083.30	-			MBHR3-50-031BBB		1,083.30
2	RETAINER RH FRT	1	19.70	-			MBHN1-50-0T1F		19.70
3	NUT,CLIP	10	3.70	-			MC274-50-133		37.00
4	FASTENER	2	3.00	-			MB45A-56-146A		6.00
5	GROMMET,SCREW	2	2.90	-			MGHP9-50-0Z5		5.80
6	FRONT FENDER RH	1	350.60	-			MB45A-52-111B		350.60
7	STAY FENDER RH FRT	1	37.40	-			MB4ZA-52-1R0A		37.40
8	MUD GUARD RH FRT	1	101.90	-			MB45A-56-130H		101.90
9	FASTENER	10	3.00	-			MB45A-56-146A		30.00
10	WHEEL,DISC 16X6.5 ALUM	1	1,156.80	-			M9965-D0-6560		1,156.80
11	VALVE,AIR TYRE	1	6.70	-			M9963-60-4140		6.70
12	FRONT ABSORBER RH	1	360.80	-			MBHS2-34-700A		360.80
13	BEARING TOP FRT ABSORBER RH	1	55.80	-			MB45A-34-38XA		55.80
14	RUBBER MOUNTING ABSORBER FRT RH	1	96.50	-			MKD35-34-380C		96.50
15	KNUCKLE FRT RH	1	402.60	-			MB45A-33-021		402.60
16	HUB WHEEL BEARING FRT RH	1	568.80	-			MB45A-33-04X		568.80
17	HEADLAMP RH	1	2,357.30	-			MBHT6-51-031A		2,357.30
18	FASTENER	1	3.50	-			MB092-51-833		3.50
TOTAL PARTS									6,680.50
TOTAL PARTS COST									6,680.50

SUPPLEMENTARY									
NO	DESCRIPTION	QTY			1st	Supp	PARTS NO	REVISED	PRICES
1									
2									
3									
TOTAL PARTS									-
TOTAL PARTS COST									-

Labour Description					REVISED	PRICES
1		TO REPLACE FRONT BUMPER,FRONT FENDER RH AND REPAIR FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS.				2,640.00

2		TO RESPRAY FRONT BUMPER,FRONT FENDER RH AND FRONT DOOR RH AND AREAS AFFECTED BY THE ACCIDENTS.		2,520.00	
3	MZ-BR-AXNSUP	TO REPLACE AXLE AND SUSPENSION MECHANISM.		660.00	
4	MZ-BR-WHEALI	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	560.00	
5	MZ-BR-WHEBAL	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NETT	120.00	
6	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	
7	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		300.00	
8	MZ-BR-SUNDRI	SUNDRIES.		50.00	
<b>REMARKS:</b> THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A <b>QUOTATION FEE OF \$400</b> WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES			TOTAL LABOUR	-	<b>7,100.00</b>
			TOTAL PARTS	-	<b>6,680.50</b>
			TOTAL	-	<b>13,780.50</b>
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	-	13,780.50
			GST 7%	-	<b>964.64</b>
			<b>GRAND TOTAL</b>	-	<b>14,745.14</b>
<b>SUPPLEMENTARY LABOUR DESCRIPTION</b>					
				<b>REVISED</b>	<b>PRICES</b>
1		#N/A			
2		#N/A			
<b>REMARKS:</b> THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A <b>QUOTATION FEE OF \$400</b> WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES			TOTAL LABOUR	-	-
			TOTAL PARTS	-	-
			TOTAL	-	-
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	-	
			GST 7%	-	-
			<b>GRAND TOTAL</b>	-	-

**TRANS EUROKARS PTE LTD**

\_\_\_\_\_  
 Authorised Signature