

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG21011220/BTF3E2

Date: 18/11/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001622773		
Claimant Vehicle No :	SJY1953T	Insured Vehicle No :	SLQ5414A		
Date of Loss:	01/11/2021	Nature of Claim:	TP	Claim No:	264897

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY1953T	Engine No:	CDL033756
Make & Model:	AUDI S3, 2.0 TFSI Quattro (M)	Chassis No:	WAUZZZ8P0BA006412
Reg. Date:	11/08/2010 (Man. Year: 2010)	Odometer:	258031 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/35 R19	Rear Tyre Size:	235/35 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,655.21	7,119.15	9,536.06	57.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,800.00	1,720.00	1,080.00	38.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,455.21	8,839.15	10,616.06	54.57
Approved Total (Overridden) (S\$)		7,050.00		
Nett Amount (S\$)	19,455.21	7,050.00	12,405.21	63.76

INSPECTION

Date of Assignment:	03/11/2021	
Date Inspected:	03/11/2021	Inspected At: Sg Auto Repair Pte Ltd (HQ) 8 Kaki Bukit Ave 4 #04-03, Premier @ Kaki Bukit Singapore 415875
Estimated Period of Repair:	6.0 days	

Adjuster: Lim Teow Guan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Nov 2021)
Parts:	144	AUDI S3 2.0 TFSI Quattro (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY1953T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	2,777.30 FL	*1,800.00 FL
2	2		*BOOT LID HINGE	Not Damaged	399.78 FL	*- FL
3	1		*BOOT LID INNER TRIM BOARD	Not Damaged	668.33 FL	*- FL
4	1		*BOOT LID LOCK	Not Damaged	333.75 FL	*- FL
5	1		*BOOT LID INNER LAMP (RHS)	Not Damaged	680.17 FL	*- FL
6	2		*BOOT LID INNER LAMP (LHS)	Not Damaged	1,360.34 FL	*- FL
7	1		*BOOT LID LOGO	Necessary	187.21 FL	*110.00 FL
8	1		*BOOT LID EMBLEM S3	Necessary	189.11 FL	*72.30 FL
9	1		*REAR BUMPER	Broken	1,999.54 FL	*1,700.00 FL
10	1		*REAR BUMPER RETAINER (LHS)	Necessary	82.17 FL	*82.17 FL
11	1		*REAR BUMPER RETAINER (RHS)	Necessary	82.17 FL	*82.17 FL
12	1		*REAR BUMPER LOWER SPOILER	Broken	599.71 FL	*559.71 FL
13	1		*REAR BUMPER LOWER SPOILER GRILLE (2PCS)	Broken (1Pc Only)	1,174.42 FL	*502.38 FL
14	1		*REAR REINFORCEMENT	Not Damaged	733.54 FL	*- FL
15	1		*END PANEL	Dented	1,572.21 FL	*696.00 FL
16	1		*END PANEL TOP GARNISH	Broken	333.54 FL	*206.00 FL
17	1		*TAIL LAMP (RHS)	Broken	788.54 FL	*788.54 FL
18	1		*TAIL LAMP BRACKET (RHS)	Broken	80.22 FL	*45.90 FL
19	1		*TAIL LAMP (LHS)	Not Damaged	788.54 FL	*- FL
20	1		*TAIL LAMP BRACKET (LHS)	Broken	80.22 FL	*45.90 FL
21	1		*REAR FENDER INNER TRIM BOARD (RHS)	Broken	880.54 FL	*560.00 FL
22	1		*REAR FENDER INNER TRIM BOARD (LHS)	Not Damaged	880.54 FL	*- FL
23	1		*REVERSE SENSOR (4PCS)	Short Circuit (1Pc Only)	1,128.84 FL	*282.21 FL
24	1		*SET REAR BUMPER CLIP	Necessary	90.00 FS	*30.00 FS
25	1		*SET END PANEL TOP GARNISH CLIP	Necessary	90.00 FS	*30.00 FS
26	1		*REAR NO. PLATE WITH CASING	Bent	50.00 FS	*50.00 FS
27	1		*SET REAR FENDER INNER TRIM BOARD CLIP	Necessary	90.00 FS	*20.00 FS
28	1		*WINDSCREEN SEALANT	Necessary	90.00 FS	*40.00 FS
29	1		*BOOT LID WEATHERSTRIP	Distorted	249.50 FL	*188.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,460.23	7,891.28
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,805.02	772.13
Total Parts (\$\$)	16,655.21	7,119.15

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,000.00	800.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	0.00
4	TO SUPPLY UNDER COATING / PUTTY ON PARTS REPLACED	New	80.00	0.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	0.00
6	DISCONNED AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET	New	150.00	0.00
7	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	80.00	60.00
8	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR (BOOT LID)	New	120.00	80.00
9	REMOVE AND REPLACE BUMPER SENSOR	New	60.00	60.00
10	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
Gross Labour Cost (S\$)			2,800.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >