



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 69M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
6	ADHESIVE:DIRECT GLAZING @\$37.00	NOT NECESSARY	222.00	-
1	PRIMER (SIKA 206 G+P)	NOT NECESSARY	80.00	-
1	ACTIVATOR	NOT NECESSARY	80.00	-
1	TRIM, WHEELARCH:FOR MB OC500 LE BUS	TO REPAIR SEE LABOUR	124.20	-
1	PANEL, SKIRT:R4, FOR MB OC500 BUS	TO REPAIR SEE LABOUR	1,442.10	-
			1,948.30	-
	<u>SPECIAL NETT ITEMS</u>			
1	SGLOVEBUS STICKERS (SN)	NECESSARY	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF TRIM, WHEELARCH:FOR MB OC500 LE BUS AND PANEL, SKIRT:R4, FOR MB OC500 BUS.		2,120.00	1,590.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		1,112.00	942.00
			3,232.00	2,532.00
	GRAND TOTAL		5,380.30	2,732.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			2,200.00

Report Ref No. NS/INC21011223/R1vce2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.