

Our reference:

21-8025

Date:

25/8/2021

c/o Assure Auto Assist Pte Ltd 23 Tuas Avenue 18 Singapore 638902

Dear Sirs

RE:

Road Traffic Accident on 12/8/2021 Abdul Aleem Bin Abdul Wahab

In accordance with your instructions received in this office on

13/8/2021

, we made arrangements to

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

examine the vehicle on

13/8/2021

at above-mentioned address. The following data was

recorded:

Vehicle details

Make	Toyota	Registration	SLA9752G
Model	Estima	Chassis	ACR500091863
Colour	Black	Gearbox	Auto
Odometer	139391km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		

Tyre Depths

Front left	215/55ZR17	85% Habilead
Front right	215/55ZR17	85% Habilead
Rear left	215/55ZR17	85% Habilead
Rear right	215/55ZR17	85% Habilead

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$9,100.00 and 8 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd Impact Analysis Academy Pte Ltd IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-8025

Date

25/8/2021

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:					
Tail gate 🗸	1	crushed	1753.60	1753.60	1585
Tail gate weather strip ✓	1	ripped.nec	285.40	285.40	✓
Tail gate logo ✓	1	necessay	66.78	66.78	✓
Tail gate emblem 'ESTIMA' ✓	1	necessay	42.35	42.35	✓
Tail gate emblem 'AERAS' ✓	1	necessay	46.13	46.13	✓
Tail gate outer garnish \checkmark	1	cracked	201.50	201.50	✓
Tail gate inner lock 🗸	1	bent-in.jammed	412.70	412.70	✓
Tail gate inner trim ✓	1	holder broken	551.80	551.80	✓
Tail gate inner lock cover 🗸	1	grazed	29.54	29.54	\checkmark
Tail gate windscreen moulding 🗸	1	necessay	188.76	188.76	120.7
Tail gate damper @\$290.90 X SVC	2	Ih reuse rh stiffened	581.80	290.90	X
Tail gate reflector @\$382.70 ✓	2	holder damaged	765.40	765.40	473.4
Tail gate centre reflector 🗸	1	damaged	233.00	233.00	✓
Tail gate outer handle X SVC	1	damaged	85.70	85.70	X
Rear bumper 🗸	1	deformed	1339.43	1339.43	715.1
Rear bumper reflector Ih 🗸	1	holder broken	55.80	55.80	✓
Rear bumper side retainer @\$50.33 🗸	2	necessay.cracked	100.66	100.66	✓
Rear end panel 🗸	1	crushed	755.40	755.40	✓
Rear end panel top garnish 🗸	1	deformed	246.05	246.05	✓
Rear end panel top garnish lower 🗸	1	deformed	165.06	165.06	✓
Rear fender inner trim @\$776.30 🗸	2	deformed	1552.60	1552.60	✓
Tail lamp @\$412.00 SVC	2	check.refix	824.00	0.00	
Rear floor panel X REPAIR	1	damaged _	1125.80	1125.80	X
Sub- Total costs		l costs	11409.26	10294.36	7638
Percentage discount: 25%			2852.32	2573.59	
Sub-1	Total cost	ts for parts	8556.95	7720.77	5729

Subsidiaries of Impact Analysis Consultant:

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

 [■] IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-8025

Date

25/8/2021

	202	
Special	Nott	Itomc.
Special	IAGIE	items.

Sub-T	otal costs	for parts	1265.00	735.00 481
Tail gate keyless sesnor 🗸	1	broken	225.00	225.00 150
Rear floor panel seal X SVC	1	necessary	85.00	85.00
Rear end panel sealant 🗸	1	necessary	40.00	40.00 🗸
Reverse camera SVC	1	refix	480.00	0.00
Rear reverse sensor 🗸	1	malfunction	280.00	280.00 200
Rear end panel top garnish clip @\$5.50 \checkmark	2	necessary	11.00	11.00 🗸
Rear bumper clip @\$5.50 ✓	8	necessary	44.00	44.00 30
Rear number plate SVC	1	reuse	50.00	0.00
Tail gate windscreen sealant \checkmark	1	necessary	50.00	50.00 🗸

Parts Repair

Total costs for parts	9821.95	8455.77
Sub- Total costs	0.00	0.00
* *	0.00	0.00

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

[■] Impact Analysis Consulting Pte Ltd
■ Impact Analysis Academy Pte Ltd
■ IA Racking Solutions Pte Ltd

Our reference

21-8025

Date

25/8/2021

Page

3

Section B: Labour Cost Calculation

No.25 Kaki Bukit Road 4

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

	Но	urly rate	19	Total	
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	45.00	23	\$ 1,035.00	600
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-con	tract work.	\$ 850.00	800
Apply rust proofing on the adjacent panels.		Sub-cont	tract work.	\$ 50.00	/
Remove and refix tailgate rear windscreen glass. (2-man job)	\$	45.00	3.5	\$ 157.50	120
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$	45.00	1.7	\$ 76.50	40
Remove and refix rear reverse camera & conduct distance safety setting	\$	45.00	1.7	\$ 76.50	40
Conduct water leak test for rear portion associated repair works	\$	45.00	1	\$ 45.00	×
Transfer of existing tailgate mechanism to new tailgate	\$	45.00	2	\$ 90.00	60
Wiring and bulb checking	\$	45.00	0.8	\$ 36.00	30
		Total la	bour cost	\$ 2,416.50	1740

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd

 [■] IA Accounting & Consultancy Pte Ltd
 ■ Infoknights International Services (Philippines)
 ■ IABN Pte Ltd
 www.iaconsultingsg.com



Our reference

21-8025

Date

25/8/2021

Section C: Summary Table of Total Repair Cost

Description	Cost	
Damaged Parts Assessment (See section A)	\$8,455.77	
Further discount	\$1,691.15	30
Recommended cost of parts replacement	\$6,764.62	(1)
Labour Cost Calculation (See section B)	\$2,416.50	(2)
Total Repair Cost (Round off to hundred)	\$9,100.00	(1) + (2)

We would recommend a sum of _	\$9,100.00	and	8	working days for repair
No further items will be approved	without our expres	ssed written agre	ement. Any sign	ificant additional
items will be subject to a supplement	entary report.			

7950.22

5 Days

-20%: 6350

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators

IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

ACTA certified Trainer, Singapore

Enterprise Singapore - Recognised Certification for Management Consultants

IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd
 Impact Analysis Academy Pte Ltd
 IA Racking Solutions Pte Ltd
- IA Accounting & Consultancy Pte Ltd
 Infoknights International Services (Philippines)
 IABN Pte Ltd
 www.iaconsultingsg.com

#06-46 Synergy @KB Singapore 41780 Hotline: **6385 1171**

No.25 Kaki Bukit Road 4