

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21011229/RVY3E2

Date: 22/06/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00012332100
Claimant Vehicle No: SLD1668D Insured Vehicle No: SGV6234D
Date of Loss: 31/10/2021 Nature of Claim: TP Claim No: SNM21D206261/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLD1668D
Make & Model: MERCEDES-BENZ CLA200, 1.3 AMG LINE (A) Engine No: 28291480385583
Reg. Date: 26/11/2020 (Man. Year: 2020) Chassis No: W1K1183872N129434
Colour: White Odometer: 25185 km
Engine Capacity: 1332 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/35Z R15 Rear Tyre Size: 245/35Z R15
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,651.00	8,745.00	10,906.00	55.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,710.00	1,830.00	1,880.00	50.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,361.00	10,575.00	12,786.00	54.73
Approved Total (Overridden) (\$\$)		8,450.00		
(\$\$)	23,361.00	8,450.00	14,911.00	63.83
+ GST 7.00/7.00% (\$\$)	1,635.27	591.50	1,043.77	63.83
Nett Amount (\$\$)	24,996.27	9,041.50	15,954.77	63.83

INSPECTION

Date of Assignment: 03/11/2021
Date Inspected: 03/11/2021 Inspected At: Wega Engineering Pte Ltd (HQ)
BLK 176 Sin Ming Drive #04-16, Sin Ming
AutoCare
Singapore 57521
Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Jun 2022)
Parts:	143	MERCEDES-BENZ CLA200 1.3 AMG LINE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1668D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cracked	1,600.00 F	*1,480.00 FL
2	1		*FRONT BUMPER RETAINER RH	Not Necessary	42.00 F	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
4	1		*FRONT FENDER LH	Buckled	720.00 F	*720.00 FL
5	1		*FRONT BUMPER GARNISH	Not Necessary	330.00 F	*- FL
6	1		*FRONT BONNET	Bent	1,850.00 F	*1,850.00 FL
7	1		*FRONT BONNET HINGE LH	Not Necessary	110.00 F	*- FL
8	1		*FRONT BONNET HINGE RH	Not Necessary	110.00 F	*- FL
9	1		*FRONT BONNET HINGE SAFETY ASSY LH	Activated	220.00 F	*220.00 FL
10	1		*FRONT BONNET HINGE SAFETY ASSY RH	Activated	220.00 F	*220.00 FL
11	1		*FRONT BUMPER SPONGE	Cracked	350.00 F	*350.00 FL
12	1		*FRONT HEADLAMP LH	Broken	3,950.00 F	*2,653.00 FL
13	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	675.00 F	*- FL
14	1		*FOGLAMP COVER LH	Cracked	105.00 F	*105.00 FL
15	1		*FRONT BUMPER LOWER GARNISH	Not Necessary	340.00 F	*- FL
16	1		*FRONT BUMPER LOWER SPOILER (CHROME)	Scratched	330.00 F	*330.00 FL
17	1		*FRONT BUMPER CENTRE GARNISH	Not Necessary	180.00 F	*- FL
18	1		*FRONT BUMPER SIDE GARNISH LH	Not Necessary	120.00 F	*- FL
19	2		*FRONT SENSOR	Not Necessary	290.00 F	*- FL
20	1		*FRONT TYRE RIM LH (AMG)	Not Necessary	2,200.00 F	*- FL
21	1		*ROCKER PANEL LH	Not Necessary	550.00 F	*- FL
22	1		*FRONT FENDER LINER LH	Not Necessary	95.00 F	*- FL
23	10		*FRONT FENDER LINER CLIPS	Necessary	80.00 FS	*30.00 FS
24	1		*FRONT ABSORBER MOUNTING LH	Not Necessary	295.00 F	*- FL
25	1		*FRONT SUSPENSION LINK LH	Not Necessary	95.00 F	*- FL
26	1		*FRONT KNUCKLE ARM LH	Not Necessary	980.00 F	*- FL
27	1		*FRONT WHEEL BEARING LH	Not Necessary	480.00 F	*- FL
28	1		*FRONT LOWER ARM LH	Not Necessary	695.00 F	*- FL
29	1		*FRONT BUMPER REINFORCEMENT	Bent	462.00 F	*462.00 FL
30	1		*WIPER TANK	Deformed	190.00 F	*190.00 FL
31	1		*SUPPORT PANEL	Cracked	670.00 F	*670.00 FL
32	1		*AIR INTAKE DUCT	Cracked	140.00 F	*140.00 FL
33	1		*FRONT AIR DUCT GRILLE	Cracked	260.00 F	*260.00 FL
34	1		*FRONT BUMPER RETAINER LH	Not Necessary	42.00 F	*- FL
35	1		*FRONT ABSORBER LH	Not Necessary	795.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,651.00	9,710.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	965.00
Total Parts (\$\$)	19,651.00	8,745.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT FRONT UNDERCARRIAGE	New	350.00	0.00
2	TO WHEEL ALIGNMENT	New	120.00	0.00
3	TO TEST & REFIT SENSOR SYSTEM	New	60.00	60.00
4	TO CHECK WIRING & SYSTEM FUNCTION	New	100.00	30.00
5	TO APPLY RUST PROOFING ON AFFECTED AREAS	New	80.00	40.00
6	TO REMOVE & REFIX REAR WINDSCREEN (NPA)	New	0.00	0.00
7	TO REPAIR, KNOCKING & WELDING FRONT ACCIDENT PORTION, FRONT BUMPER, FRONT FENDER LH, FRONT BONNET, ROCKER PANEL	New	1,500.00	850.00
8	TO RESPRAY FRONT BUMPER, FRONT BONNET, FRONT FENDER LH, ROCKER PANEL LH, FRONT DOOR LH	New	1,400.00	750.00
9	TOWING	New	100.00	100.00
Gross Labour Cost (\$\$)			3,710.00	1,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >