

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011230/UVF3E2

**Date:** 03/12/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1001470779

**Claimant Vehicle No :** VEN9960

**Insured Vehicle No :** SKV162U

Date of Loss: 26/10/2021

Nature of Claim: TP

Claim No: 264693

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **VEN9960**

Make & Model: MERCEDES-BENZ CLA180 DBA-117342, 1.6 (A)

Engine No: 27091031078268

Reg. Date: 17/03/2020 (Man. Year: 2016)

Chassis No: WDD1173422N418145

Colour: Red

Odometer: 41266 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/40 R18

Rear Tyre Size: 225/40 R18

Front Left Side: Continental 7 mm

Rear Left Side: Continental 7 mm

Front Right Side: Continental 7 mm

Rear Right Side: Continental 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,749.10	2,158.95	1,590.15	42.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	720.00	930.00	56.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,399.10</b>	<b>2,878.95</b>	<b>2,520.15</b>	<b>46.68</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,300.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,399.10</b>	<b>2,300.00</b>	<b>3,099.10</b>	<b>57.40</b>

### INSPECTION

Date of Assignment: 03/11/2021

Date Inspected: 05/11/2021 Inspected At:

Hup Motor Trading & Service (HQ)  
Blk 9004 Tampines Street 93, #01-120  
Singapore 528838

Estimated Period of Repair: 3.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 03 Dec 2021)

**Parts:** 143      MERCEDES-BENZ CLA180 DBA-117342 1.6 (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for VEN9960)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Deformed	1,860.00 FL	*1,739.17 FL
2	1		*FRONT BUMPER REINFORCEMENT	Repair	365.00 FL	*- FL
3	1		*FRONT BUMPER DAMPER	Not Necessary	155.00 FL	*- FL
4	1		*FRONT LOWER GRILLE	Torn	1,275.00 FL	*495.00 FL
5	1		*FRONT BUMPER N/S AIR DUCT	Not Necessary	98.00 FL	*- FL
6	2		*FRONT BUMPER O/S & N/S SIDE BRACKET	Not Necessary	76.00 FL	*- FL
7	1		*SET BUMPER RIVETS	Necessary	252.00 FL	*80.00 FL
8	1		*FRT BUMPER LOGO	Necessary	68.00 FL	*68.00 FL
9	1		*FRT LICENCE PLATE	Cracked	15.00 FS	*15.00 FS
					<b>Sub Total (S\$)</b>	<b>4,164.00      2,397.17</b>
					<b>- List Item Discount on L Items 10.00/10.00% (S\$)</b>	<b>414.90      238.22</b>
					<b>Total Parts (S\$)</b>	<b>3,749.10      2,158.95</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	20.00
2	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS, TO JACK, STRAIGHTEN & KNOCKING OUT NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS	New	750.00	300.00
3	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	850.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,650.00</b>	<b>720.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >