#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI21011231/T1TF3E2

**Date:** 26/11/2021

**REFERENCE** 

Handling Insurer: Tokio Marine Insurance Singapore Ltd Policy No: MT105729

Claimant Vehicle Claimant Vehicle Claimant Vehicle No: ON/40470

No: SHA6004A Insured Vehicle No: SJV4017S

Date of Loss: 02/11/2021 Nature of Claim: TP Claim No: M2105097

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SHA6004A

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A) Engine No: G4LEKU295392

Reg. Date: 26/06/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU164364

Colour: Blue Odometer: 342686 km

Engine Capacity: 1580 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Good

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,565.68	2,299.04	2,266.64	49.65
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,760.00	880.00	880.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,336.68	3,190.04	3,146.64	49.66
+ GST 7.00/7.00% (S\$)	443.57	223.30	220.27	49.66
Nett Amount (S\$)	6,780.25	3,413.34	3,366.91	49.66

**INSPECTION** 

Date of Assignment: 03/11/2021 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 03/11/2021 Inspected At: 59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

# **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2021)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SHA6004A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*BOOTLID ASSY	Repair	2,480.40 FL	-	*- FL
2	1		*BOOTLID EMBLEM-HYBRID	Necessary	24.30 FL	-	*24.30 FL
3	1		*BOOTLID EMBLEM-IONIQ	Necessary	31.30 FL	-	*31.30 FL
4	1		*REAR BUMPER	Deformed	459.40 FL	-	*459.40 FL
5	1		*REAR BUMPER REINFORCEMENT	Cracked	394.80 FL	-	*394.80 FL
6	2		*REAR BUMPER REINFORCEMENT BRKT RH/LH	Bent	276.20 FL	-	*276.20 FL
7	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	-	*451.25 FL
8	1		*REAR BUMPER LOWER MOULDING	Not Necessary	155.00 FL	-	*- FL
9	2		*REAR BUMPER REFLECTOR RH/LH	Not Necessary	82.90 FL	-	*- FL
10	1		*REAR BUMPER TOW COVER	Deformed	98.80 FL	-	*98.80 FL
11	1		*REAR BUMPER FOGLAMP	Cracked	201.50 FL	-	*201.50 FL
12	1		*BOOTLID COMFORTDELGRO	Necessary	35.00 F	-	*35.00 F
13	1		*BOOTLID 65521111	Necessary	35.00 F	-	*35.00 F
14	1		*BOOTLID APPS STICKER	Necessary	40.00 F	-	*40.00 F
15	1		*REVERSE SENSORS	Necessary	180.00 F	-	*180.00 F
16	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 F
17	2		*REAR WINDSCREEN SEALANTS	Not Necessary	92.00 F	-	*- F
18	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
19	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	Necessary	200.00 F	-	*200.00 F
20	1		*BOOTLID ADVERTISEMENT STICKER	Necessary	100.00 F	-	*100.00 F
<u>Sup</u>	<u>pleme</u>	entary #1					
21	1		*REAR BUMPER SIDE UNDER COVER LH	Torn	108.00 FL	-	*108.00 FL
F=Fra	anchise	part. L=ListI	temDisc.		P		
				Sub Total (S\$)	5,522.85	2,712.55	
			- List Item Discount on L Items 20	.00/20.00% (S\$)	957.17	413.51	
				Total Parts (S\$)	4,565.68		2,299.04

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

No Qt	y Particulars		Repairer's	Amount
Miscella	ineous Items			
1 1	OD/TP Case (Insurer)		11.00	11.00
		Sub Total (S\$)	11.00	11.00

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	800.00	350.00
2	SPRAY PAINTING	New	600.00	500.00
3	R/I REAR WINDSCREEN GLASSES	New	240.00	0.00
4	R/I REVERSE SENSORS	New	120.00	30.00
		Gross Labour Cost (S\$)	1,760.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >