

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011233/AEA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700094389
Claimant Vehicle No :	SLD4820K	Insured Vehicle No :	SLV4672B
Date of Loss:	31/10/2021	Nature of Claim:	TP
		Claim No:	3581410530SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD4820K	Engine No:	M16A2025094
Make & Model:	SUZUKI VITARA, 1.6 (A)	Chassis No:	TSMLYD21S00199202
Reg. Date:	20/06/2016 (Man. Year: 2016)	Odometer:	59052 km
Colour:	Black		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,720.50	4,680.50	3,040.00	39.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,380.00	2,200.00	2,180.00	49.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,100.50	6,880.50	5,220.00	43.14
Approved Total (Overridden) (S\$)		5,500.00		
(S\$)	12,100.50	5,500.00	6,600.50	54.55
+ GST 7.00/7.00% (S\$)	847.04	385.00	462.04	54.55
Nett Amount (S\$)	12,947.54	5,885.00	7,062.54	54.55
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,587.00		
Global Sum Settlement (S\$)		6,580.00		

INSPECTION

Date of Assignment:	03/11/2021	Cn Motors Pte Ltd (HQ)
Date Inspected:	03/11/2021 Inspected At:	1 KAKI BUKIT AVENUE 6 BLK C #01-41
		AUTOBAY @ KAKI BUKIT
		Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	971.00 FL	*971.00 FL
2	1		*REAR BUMPER	Deformed	382.00 FL	*382.00 FL
3	1		*REAR BUMPER CENTER GARNISH	Cut	57.00 FL	*57.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	226.00 FL	*226.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Necessary	36.00 FL	*36.00 FL
6	2		*REAR BUMPER REFLECTOR	Cracked	36.00 FL	*36.00 FL
7	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	744.00 FL	*372.00 FL
8	1		*REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	78.00 FL	*- FL
9	1		*REAR TAILGATE	Dented	1,005.00 FL	*1,005.00 FL
10	1		*REAR TAILGATE LOCK	Damaged	164.00 FL	*164.00 FL
11	1		*REAR TAILGATE INNER TRIM BOARD	Cracked	325.00 FL	*325.00 FL
12	2		*REAR TAILGATE LAMP	Not Necessary	498.00 FL	*- FL
13	1		*REAR WEATHERSTRIPE	Cut	143.00 FL	*143.00 FL
14	1		*REAR END PANEL	Dented	414.00 FL	*414.00 FL
15	2		*REAR END PANEL AIR VENT	Cracked	60.00 FL	*60.00 FL
16	1		*REAR END PANEL TOP GARNISH	Deformed	150.00 FL	*150.00 FL
17	1		*REAR SPARE TYRE COMPARTMENT PANEL	Repair	272.00 FL	*- FL
18	1		*REAR SPARE TYRE TOP BOARD	Deformed	620.00 FL	*225.00 FL
19	1		*REAR END PANEL KEYLESS SENSOR	Not Necessary	65.00 FL	*- FL
20	1		*REAR END PANEL KEYLESS BUZZER	Not Necessary	80.00 FL	*- FL
21	2		*REAR TAILLAMP	Cut	724.00 FL	*724.00 FL
22	1		*REAR FENDER INNER TRIM BOARD LH	Not Necessary	438.00 FL	*- FL
23	1		*REAR EXHAUST MUFFLER	Repair	756.00 FL	*- FL
24	2		*REAR EXHAUST MUFFLER RUBBER MOUNTING	Not Necessary	46.00 FL	*- FL
25	1		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
26	2		*REAR TAILLAMP CLIPS	Necessary	24.00 FS	*24.00 FS
27	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	60.00 FS	*10.00 FS
28	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*60.00 FS
29	1		*REAR TAILGATE WINDSCREEN GLASS SEALANT	Necessary	120.00 FS	*60.00 FS
30	1		*REAR NUMBER PLATE WITH CASING	Not Necessary	60.00 FS	*- FS
31	1		*REAR SPARE TYRE TOP TRIM BOARD	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,964.00	5,474.00
- List Item Discount on L Items 15.00/15.00% (\$\$)	1,243.50	793.50
Total Parts (\$\$)	7,720.50	4,680.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	900.00
2	LABOUR FOR SPRAYPAINTING	New	1,400.00	800.00
3	WIRING CHECK	New	80.00	30.00
4	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	200.00	80.00
5	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS	New	300.00	60.00
6	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE	New	250.00	80.00
7	LABOUR FOR REMOVE & REFIX REAR TAILGATE WINDSCREEN GLASS	New	150.00	120.00
8	LABOUR FOR REMOVE AND REFIX OF REVERSE SENSOR	New	100.00	50.00
9	LABOUR FOR REMOVE AND REFIX OF UPHOLSTERY	New	100.00	80.00
Gross Labour Cost (\$\$)			4,380.00	2,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >