

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011237/KGS3Q2**Date:** 14/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900080906-02
Claimant Vehicle No :	SKV4183H	Insured Vehicle No :	SMQ58R
Date of Loss:	01/11/2021	Nature of Claim:	TP
		Claim No:	4417888255SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKV4183H	Engine No:	PE20672451
Make & Model:	MAZDA 6, 2.0 SEDAN (A)	Chassis No:	JM6GJ1072G0213506
Reg. Date:	16/09/2015 (Man. Year: 2015)	Odometer:	101644 km
Colour:	Metallic Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,522.37	2,086.41	2,435.96	53.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,560.00	715.00	1,845.00	72.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,082.37	2,801.41	4,280.96	60.45
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	7,082.37	2,200.00	4,882.37	68.94
+ Car Rental (4.0 x S\$110.00/day) (\$\$)		440.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,647.45		

INSPECTION

Date of Assignment:	03/11/2021	
Date Inspected:	15/11/2021	Inspected At: Lim Yew Boo Spray Paint Co (HQ) Blk 10 Sin Ming Industrial Estate, #01-10 Singapore 575645
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	1,231.50 FL	*1,231.50 FL
2	1		*REAR BUMPER BEAM	Repair	538.30 FL	*- FL
3	2		*REAR BUMPER RETAINER	Serviceable	82.00 FL	*- FL
4	1		*REAR BUMPER TOWING COVER	Serviceable	120.00 FL	*- FL
5	5		*REAR BUMPER FASTENER	Necessary	40.00 FL	*40.00 FL
6	5		*REAR BUMPER EXTENSION FASTENER	Not Necessary	40.00 FL	*- FL
7	5		*REAR BUMPER EXTENSION GROMMET SCREW	Not Necessary	40.00 FL	*- FL
8	1		*REAR BOOT LID	Bent	1,115.00 FL	*1,115.00 FL
9	1		*REAR LID RUBBER	Serviceable	135.60 FL	*- FL
10	1		*REAR LID LOCK (UPPER)	Repair	186.20 FL	*- FL
11	1		*REAR TAILEND PANEL	Repair	700.10 FL	*- FL
12	1		*REAR EMBLEM LOGO	Necessary	55.50 FN	*55.50 FN
13	1		*REAR EMBLEM MAZDA 6	Necessary	74.60 FN	*74.60 FN
14	1		*REAR EMBLEM SKY ACTIVE	Necessary	66.80 FN	*66.80 FN
15	1		*REAR LID CHROME (CENTRE)	Serviceable	302.00 FS	*- FS
16	2		*REAR LID CHROME (SIDE)	Serviceable	301.00 FS	*- FS
17	1		*REAR TAILEND PANEL TEROSTAT SEALANT	Not Necessary	54.20 FS	*- FS
18	1		*SET REAR REVERSE SENSOR	Serviceable	250.00 FS	*- FS
19	1		*REAR NO PLATE (EMBOSS) +HOLDER	Serviceable	55.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	5,387.80	2,583.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	845.74	477.30
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	19.69	19.69
Total Parts (\$\$)	4,522.37	2,086.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO APPLY RUST-PROOFING ON REPAIRED /REPLACED PANELS	New	120.00	0.00
2	TO REPLACE REVERSE SENSOR SET & CHECK WIRING FUNCTIONS	New	60.00	15.00
3	TO CHECK WATER SEEPAGE	New	60.00	0.00
4	TO REMOVE ,CHECK & REPAIR /REPLACE EXHAUST SILENCER	New	120.00	0.00
5	TO REPAIR ,PANEL BEAT ,CUT & WELD ON REPLACED PANEL,REALIGN /STRAIGHTEN ON AFFECTED AREA & LABOUR TO REPLACE ABOVE PARTS	New	1,000.00	300.00
6	TO PUTTY ,PRIMER & SPRAY PAINT ON REAR BOOT LID ,REAR END PANEL,REAR BEAM,REAR BUMPER ,REAR REVERSE SENSOR USING 2K PAINT	New	1,200.00	400.00
Gross Labour Cost (\$\$)			2,560.00	715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >