



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 777Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR DOOR O/S	DENTED	1,199.80	1,199.80
1	REAR DOOR FRAME GARNISH O/S	NOT NECESSARY	121.10	-
1	SET REAR DOOR INNER BLACK STICKER O/S	NECESSARY	75.00	75.00
1	REAR DOOR OUTER CHROME MOULDING O/S	NOT NECESSARY	288.30	-
1	REAR DOOR INNER RUBBER O/S	NOT NECESSARY	379.60	-
1	REAR DOOR LOWER HINGE O/S	SERVICEABLE	98.00	-
1	CENTRE PILLAR O/S	TO REPAIR SEE LABOUR	645.20	-
	LESS 25% DISCOUNT		-701.75	-318.70
			2,105.25	956.10
	<u>LABOUR</u>			
	TO CHECK WIRING.	NOT NECESSARY	50.00	-
	TO SPRAY RUST PROOFING.		50.00	30.00
	TO TRANSFER REAR DOOR MECHANISM.		120.00	60.00
	TO RESET & REPROGRAMME SYSTEM.		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF CENTRE PILLAR O/S.		420.00	300.00
	TO PUTTY & SPRAY PAINTING.		500.00	400.00
			1,260.00	850.00
	GRAND TOTAL		3,365.25	1,806.10
	RECOMMENDED COST OF REPAIRS			1,806.10

Report Ref No. CS/SMO21011246/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.