

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 08 Sep 2022

Preliminary Advice

Vehicle No	: XE3791U	Accident Date	: 12/10/2021
Make	: CAMC	Policy No.	:
	HN3251X40C3M6		DMCVSNA00101152100
Assignment Date	: 03/11/2021	Excess	: S\$1,500.00
Date of Inspection	: 05/11/2021	Est. Duration of Repair	: 0
Inspection At	: GOLDBELL ENGINEERING PTE LTD (TUAS) 10 TUAS AVE 18 SINGAPORE 638894		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 83,877.00
Revised Amount	:S\$ 77,999.00
Check Items (Estimated)	:S\$ 0.00
Total	:S\$ 77,999.00

Lump Sum Repair	:S\$ 62,300.00
-----------------	----------------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 100,000.00
COE / PARF Rebate	:S\$ 35,621.00

Salvage Value	:S\$
Margin for Repair	:S\$ 64,379.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.