

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011250/UVY3N2**Date:** 16/11/2021**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNW00009682102

**Claimant Vehicle
No :** GBH7510H**Insured
Vehicle No :** SMD9444T

Date of Loss: 01/11/2021

Nature of Claim: TP

Claim
No: SNM21D206274/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBH7510H**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M)

Engine No: 1KD2817089

Reg. Date: 18/09/2018 (Man. Year: 2018)

Chassis No: JTFAT35Y10K211294

Colour: Silver

Odometer: 73110 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

Front Tyre Size: 195R15

Rear Tyre Size: 155R12(D)

Front Left Side: APLUS 6 mm

Rear Left Side: Windforce 6/6 mm

Front Right Side: APLUS 6 mm

Rear Right Side: Windforce 6/6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 5,507.49 | 2,285.87 | 3,221.62 | 58.50 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,790.00 | 1,470.00 | 320.00 | 17.88 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 7,297.49 | 3,755.87 | 3,541.62 | 48.53 |
| Approved Total (Overridden) (\$\$) | | 3,000.00 | | |
| Nett Amount (\$\$) | 7,297.49 | 3,000.00 | 4,297.49 | 58.89 |

INSPECTION

Date of Assignment: 03/11/2021

Date Inspected: 09/11/2021 Inspected At:

Yew Hok Auto Services (HQ)
1 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki
Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 15 Nov 2021) | |
| Parts: | N/A | TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBH7510H) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--------------------------------------|---------------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Dented/Bent | 1,482.50 FL | *1,482.50 FL |
| 2 | 1 | | *SET TAILGATE STICKER TOYOTA | Necessary | 180.60 FL | *180.60 FL |
| 3 | 1 | | *TAILGATE STICKER DYNA | Necessary | 58.60 FL | *58.60 FL |
| 4 | 1 | | *TAILGATE LOWER MEMBER | Repair | 489.60 FL | *- FL |
| 5 | 4 | | *TAILGATE HINGES | Repair | 262.00 FL | *- FL |
| 6 | 1 | | *TAILGATE LOWER STOPPER O/S | Cut | 48.60 FL | *48.60 FL |
| 7 | 1 | | *TAILGATE LOWER STOPPER BRACKET O/S | Bent | 110.50 FL | *110.50 FL |
| 8 | 1 | | *TAILLAMPS-L/R | O/s Cracked/Not Necessary | 582.66 FL | *291.33 FL |
| 9 | 1 | | *TAILLAMP PANELS-L/R | O/s Bent/Not Necessary | 516.20 FL | *258.10 FL |
| 10 | 1 | | *SIDEGATE-RH | Repair | 1,865.90 FL | *- FL |
| 11 | 1 | | *SIDEGATE LOCK HINGE-RH | Bent | 186.95 FL | *186.95 FL |
| 12 | 1 | | *REAR LICENCE PLATE PANEL | Bent | 110.65 FL | *110.65 FL |
| 13 | 1 | | *REAR SPARE WHEEL CARRIER | Not Necessary | 361.90 FL | *- FL |
| 14 | 1 | | *SET REAR REVERSE SENSOR WITH HOLDER | Cracked/Damaged | 300.00 FS | *200.00 FS |
| 15 | 1 | | *REAR NO PLATE | Bent | 45.00 FS | *20.00 FS |
| 16 | 1 | | *REAR STICKER 70KM/H | Necessary | 10.00 FS | *10.00 FS |
| 17 | 1 | | *REAR STICKER 13PAX | Necessary | 10.00 FS | *10.00 FS |
| 18 | 1 | | *TAILGATE ALUMINIUM BOARD | Not Necessary | 450.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$) | 7,071.66 | 2,967.83 |
| - List Item Discount on L Items 25.00/25.00% (\$) | 1,564.17 | 681.96 |
| Total Parts (\$) | 5,507.49 | 2,285.87 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TO CHECK REAR ELECTRICAL WIRING | New | 50.00 | 20.00 |
| 2 | TO REMOVE,REFIX REAR REVERSE SENSOR | New | 60.00 | 40.00 |
| 3 | TO RESPRAY UNDERCOATING | New | 80.00 | 50.00 |
| 4 | TO RESPRAY PAINTING AND ETC | New | 800.00 | 680.00 |
| 5 | PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS | New | 800.00 | 680.00 |
| Gross Labour Cost (\$) | | | 1,790.00 | 1,470.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >