

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011253/EPA3Q2**Date:** 19/07/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100417367
Claimant Vehicle No :	SBS6367D	Insured Vehicle No :	SBC9663M
Date of Loss:	02/11/2021	Nature of Claim:	TP
		Claim No:	2194399335SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBS6367D		
Make & Model:	MERCEDES-BENZ CITARO O530, 6.4 L AT TURBO	Engine No:	902926C0994248
	ABS (A)		
Reg. Date:	01/03/2013 (Man. Year: 2012)	Chassis No:	WEB62808323124774
Colour:	Multi-colour	Odometer:	534178 km
Engine Capacity:	6374 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	295/80 R22.5	Rear Tyre Size:	295/80 R22.5
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,074.10	1,976.89	1,097.21	35.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,240.00	1,940.00	1,300.00	40.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,314.10	3,916.89	2,397.21	37.97
+ GST 7.00/7.00% (S\$)	441.99	274.18	167.81	37.97
Nett Amount (S\$)	6,756.09	4,191.07	2,565.02	37.97
+ Loss of Use (4.0 x S\$250.00/day) (S\$)		1,000.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,193.07		
Global Sum Settlement (S\$)		5,100.00		

INSPECTION

Date of Assignment:	03/11/2021		
Date Inspected:	05/11/2021	Inspected At:	Tower Transit Singapore Pte Ltd (HQ) 21 Bulim Drive, Bulim Bus Depot Singapore 648170
Estimated Period of Repair:	3.0 days		

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NS FRONT BUMPER BRACKETS	Bent	311.30 F	*311.30 FL
2	1		*NSF BUMPER	Broken	1,207.00 F	*1,207.00 FL
3	1		*HEADLAMP LH ASSY	Not Necessary	877.56 F	*- FL
4	1		*NS BLINKER /SIGNAL LAMP	Missing	113.98 F	*113.98 FL
5	1		*FRONT BUMPER N/S ANGLE	Broken	241.42 F	*241.42 FL
6	1		*NS FRONT BUMPER BRACKETS	Bent	257.30 F	*257.30 FL
7	1		*NS FRONT BUMPER LOCK	Bent	65.54 F	*65.54 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,074.10	2,196.54
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	219.65
Total Parts (\$)	3,074.10	1,976.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE PARTS NOS 1-5	New	1,950.00	1,300.00
2	TO PERFORM ELECTRICAL WIRING CHECK AND REPLACEMENTS OF DAMAGED INSTERNAL WIRING	New	650.00	0.00
3	SPRAY PAINTING -NFS BUMPER	New	640.00	640.00
			Gross Labour Cost (\$)	3,240.00
				1,940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >