



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2200172

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 07/01/2022
Reference CC6/CTI21011259/Ara3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SFN 4808R
Insured Veh. XE 4233H
Claim No. SNM21D206255/LKKDS
Policy No. DMCVSNW00090032101
Accident Date 01/11/2021
Inspection Date 02/11/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC6/CTI21011259/Ara3q2 Date: 07/01/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 4233H	Veh. Inspected	SFN 4808R	
Policy No.	DMCVSNW00090032101	Coverage (\$)	0.00	
Claim No.	SNM21D206255/LKKDS	Excess (\$)	0.00	
Assign From		Assign Date	02/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JHMRN68408S202708	Colour	BLACK	
Odometer	306925 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	ROADBOSS	6 mm	
L/H Front Tyre	205/55 R16	ROADBOSS	6 mm	
R/H Rear Tyre	205/55 R16	ROADBOSS	6 mm	
L/H Rear Tyre	205/55 R16	ROADBOSS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/11/2021	Inspection Date	02/11/2021	
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFN 4808R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH REAR DOOR	DISTORTED	1,652.30	961.00
2	RH REAR DOOR HINGE @\$189.10	NOT NECESSARY	378.20	-
1	RH REAR DOOR CHECKER	NOT NECESSARY	148.80	-
1	RH REAR DOOR WEATHER STRIPE	CUT	198.60	198.60
1	RH REAR DOOR LOCK	DAMAGED	315.60	315.60
1	RH REAR DOOR SWITCH	NOT NECESSARY	55.60	-
1	RH REAR DOOR POWER WINDOW MOTOR	DAMAGED	548.10	398.00
1	RH REAR DOOR POWER WINDOW REGULSTOR GEAR	DAMAGED	389.60	389.60
1	RH REAR DOOR INNER TRIM BOARD	CRACKED	498.40	498.40
1	RH REAR DOOR BLACKER STICKER	NECESSARY	150.00	150.00
1	RH REAR DOOR WINDOW GLASS	CUT	498.70	498.70
1	RH REAR DOOR WINDOW GLASS OUTER MOULDING	DEFORMED	161.90	161.90
1	RH REAR DOOR OUTER HANDLER	DAMAGED	130.60	130.60
1	RH REAR DOOR WINDOW GLASS CHANNEL	NOT NECESSARY	165.60	-
1	RH REAR DOOR WIRE HARNESS	NOT NECESSARY	486.70	-
1	RH REAR DOOR INNER WEATHER STRIPE	NOT NECESSARY	191.60	-
1	RH CENTER DOOR PILLAR OUTER	NOT NECESSARY	689.60	-
1	RH REAR STEP INNER GARNISH	NOT NECESSARY	125.60	-
1	RH REAR FENDER	DISTORTED	1,742.20	972.00
1	RH REAR FENDER INNER PANEL	DISTORTED	1,474.30	794.00
1	RH REAR FENDER INNER TRIM BOAD	CRACKED	697.10	285.00
1	RH REAR FENDER INNER COWLING	NOT NECESSARY	197.60	-
1	RH REAR FENDER AIR VENT	NOT NECESSARY	69.20	-
1	RH REAR WHEEL HOUSE PANEL	DISTORTED	1,726.80	850.00
1	RH REAR FENDER QUARTER GLASS WITH MOULDING	NOT NECESSARY	768.00	-
1	RH ROCKER PANEL OUTER	TO REPAIR SEE LABOUR	948.70	-
1	REAR BUMPER	DISTORTED	688.90	688.90
1	REAR BUMPER SIDE RETAINER RH	DAMAGED	64.20	32.00
1	RH REAR TAILLAMP	CRACKED	497.60	366.00
1	RH REAR TAILLAMP LOWER BRACKET	NOT NECESSARY	28.60	-

Report Ref No. CC6/CTI21011259/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RH REAR TAILLAMP INNER PANEL	TO REPAIR SEE LABOUR	269.30	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	486.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	198.30	-
1	REAR SPARE TYRE COMPARTMENT PANEL	TO REPAIR SEE LABOUR	597.00	-
1	REAR SPARE TYRE COMPARTMENT TOP BOARD	NOT NECESSARY	394.20	-
1	REAR SPARE TYRE COMPARTMENT GARNISH	NOT NECESSARY	295.20	-
1	RH REAR CHASSIS FRAME	TO REPAIR SEE LABOUR	1,426.80	-
1	RH REAR CHASSIS FRAME TOP PANEL	TO REPAIR SEE LABOUR	476.35	-
1	REAR EXHAUST MUFFLER	NOT NECESSARY	986.30	-
1	REAR EXHAUST MUFFLER SHIELD	NOT NECESSARY	189.40	-
1	REAR EXHAUST CENTER PIPE	NOT NECESSARY	1,276.40	-
2	REAR EXHAUST MUFFLER RUBBER MOUNTING @\$32.10	NOT NECESSARY	64.20	-
1	RH REAR LOWER ARM	BENT	658.90	395.00
1	RH REAR KNUCKLE ARM	DAMAGED	558.70	361.00
1	RH REAR SHOCK ABSORBER	BENT	424.70	325.00
1	RH REAR WHEEL BEARING HUP	DAMAGED	294.60	294.60
1	RH REAR ABS SENSOR	NOT NECESSARY	242.30	-
1	REAR CROSS MEMBER (ADDITIONAL)	BENT	910.50	910.50
1	RH REAR TRAILING ARM (ADDITIONAL)	BENT	437.40	138.00
	LESS 20% DISCOUNT		-5,175.13	-2,022.88
			20,700.52	8,091.52
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	RH REAR DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	RH REAR FENDER INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	RH REAR FENDER SEALANT (SN)	NECESSARY	100.00	50.00
1	RH REAR STEP CHROME MOULDING (SN)	NOT NECESSARY	280.00	-
1	RH REAR RIM (SN)	CUT	950.00	500.00
1	RH REAR TYRE (SN)	PUNCTURE	320.00	180.00

Report Ref No. CC6/CTI21011259/Ara3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	280.00	-
			2,110.00	820.00
	LABOUR			
	LABOUR FOR PANEL BEATING.INCLUSIVE OF THE REPAIR OF RH ROCKER PANEL OUTER ,RH REAR TAILLAMP INNER PANEL,REAR END PANEL,REAR SPARE TYRE COMPARTMENT PANEL,RH REAR CHASSIS FRAME AND RH REAR CHASSIS FRAME TOP PANEL.		3,500.00	1,400.00
	LABOUR FOR SPRAYPAINTING.		2,500.00	1,200.00
	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS .	NOT NECESSARY	150.00	-
	LABOUR FOR REMOVE & TRANSFER RH REAR DOOR FITTING.		200.00	80.00
	LABOUR FOR REMOVE & RENEW RH REAR UNDER CARRIAGE.		300.00	300.00
	TO CONDUCT WHEEL ALIGNMENT.		150.00	80.00
	WIRING CHECK .		80.00	30.00
	TO APPLY RUST PROOF /TUFF COAT ON ACCIDENT AREAS.		200.00	100.00
	TOW FEE.		200.00	120.00
	LABOUR FOR REMOVE & RENEW REAR EXHAUST MUFFLER ,TO REPAIR & STRAIGHTEN REAR EXHAUST PIPE.	NOT NECESSARY	300.00	-
	LABOUR FOR REMOVE & RENEW RH REAR FENDER QUARTER GLASS.		150.00	60.00
			7,730.00	3,370.00
GRAND TOTAL			30,540.52	12,281.52
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,800.00

Report Ref No. CC6/CTI21011259/Ara3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFN 4808R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFN 4808R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SFN 4808R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

