

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011273/BTF3E2

**Date:** 19/11/2021

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29115298QMX
<b>Claimant Vehicle No :</b>	SMY7013G	<b>Insured Vehicle No :</b>	SMH5998S
Date of Loss:	02/11/2021	Nature of Claim:	TP
		Claim No:	638696

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY7013G	Engine No:	PE21267323
Make & Model:	MAZDA 6, 2.0 SEDAN EXECUTIVE 2WD (A)	Chassis No:	JM6GL1072K0314809
Reg. Date:	15/07/2019 (Man. Year: 2019)	Odometer:	39619 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,259.68	6,640.00	9,619.68	59.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,800.00	2,270.00	1,530.00	40.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,059.68</b>	<b>8,910.00</b>	<b>11,149.68</b>	<b>55.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>7,100.00</b>		
<b>Nett Amount (S\$)</b>	<b>20,059.68</b>	<b>7,100.00</b>	<b>12,959.68</b>	<b>64.61</b>

### INSPECTION

Date of Assignment:	05/11/2021	8 Kaki Bukit Avenue 4, #04-03, Premier@Kaki Bukit
Date Inspected:	05/11/2021 Inspected At:	Repairer: FC Garage (HQ)
Estimated Period of Repair:	7.0 days	

**Adjuster:** Lim Teow Guan

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
<b>Parts:</b>	143	MAZDA 6 2.0 SEDAN EXECUTIVE 2WD (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMY7013G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	1,235.00 FL	*1,135.00 FL
2	1		*BOOT LID WEATHERSTRIP	Not Damaged	184.80 FL	*- FL
3	1		*BOOT LID LOGO	Necessary	71.50 FL	*54.20 FL
4	1		*BOOT LID EMBLEM MAZDA 6	Necessary	72.20 FL	*53.40 FL
5	1		*BOOT LID EMBLEM SKYACTIVE	Necessary	86.60 FL	*64.00 FL
6	1		*BOOT LID LAMP (RHS)	Not Damaged	1,073.70 FL	*- FL
7	1		*BOOT LID LAMP (LHS)	Not Damaged	1,073.70 FL	*- FL
8	1		*BOOT LID INNER TRIM BOARD	Torn	350.50 FL	*212.60 FL
9	1		*BOOT LID CHROME STRIP	Not Damaged	256.50 FL	*- FL
10	1		*BOOT LID LOCK	Jammed	180.70 FL	*161.00 FL
11	1		*REAR BUMPER	Broken	1,199.00 FL	*997.40 FL
12	1		*REAR BUMPER RETAINER (RHS)	Necessary	61.00 FL	*47.40 FL
13	1		*REAR BUMPER RETAINER (LHS)	Necessary	61.00 FL	*47.40 FL
14	1		*REAR BUMPER TOWING COVER (LHS)	Missing	27.50 FL	*12.00 FL
15	1		*REAR BUMPER TOWING COVER (RHS)	Broken	27.50 FL	*12.00 FL
16	1		*REAR BUMPER REFLECTOR (RHS)	Broken	61.10 FL	*61.10 FL
17	1		*REAR BUMPER REFLECTOR (LHS)	Not Damaged	61.10 FL	*- FL
18	1		*REAR REINFORCEMENT	Dented	638.30 FL	*586.00 FL
19	1		*END PANEL	Dented	800.10 FL	*576.10 FL
20	1		*END PANEL TOP GARNISH	Broken	189.00 FL	*189.00 FL
21	1		*TAIL LAMP (RHS)	Broken	2,102.90 FL	*1,516.00 FL
22	1		*TAIL LAMP BRACKET (RHS)	Not Damaged	425.90 FL	*- FL
23	1		*TAIL LAMP RADAR (RHS)	Broken	1,516.20 FL	*1,516.20 FL
24	1		*TAIL LAMP (LHS)	Not Damaged	2,102.90 FL	*- FL
25	1		*TAIL LAMP BRACKET (LHS)	Not Damaged	425.90 FL	*- FL
26	1		*TAIL LAMP RADAR (LHS)	Not Damaged	1,516.20 FL	*- FL
27	1		*REAR FENDER INNER TRIM BOARD (RHS)	Torn	621.70 FL	*621.70 FL
28	1		*SPARE TYRE COMPARTMENT SIDE GARNISH (RHS)	Not Damaged	186.90 FL	*- FL
29	1		*EXHAUST MUFFLER	Repair	1,585.70 FL	*- FL
30	1		*EXHAUST MUFFLER HEAT SHIELD	Not Damaged	79.50 FL	*- FL
31	1		*BOOT LID HANDLE POCKET	Missing	112.50 FL	*112.50 FL
32	10		*REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
33	10		*END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*30.00 FS
34	10		*BOOT LID INNER TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
35	1		*REAR REVERSE SENSOR	Short Circuit	300.00 FS	*200.00 FS
36	1		*REAR NO PLATE WITH CASING	Not Damaged	50.00 FS	*- FS
37	1		*REAR FENDER RHS	Repair	1,312.50 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>20,199.60</b>	<b>8,235.00</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	<b>3,939.92</b>	<b>1,595.00</b>
<b>Total Parts (\$\$)</b>	<b>16,259.68</b>	<b>6,640.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	New	1,000.00	600.00
2	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT AFFECTED AREAS	New	1,200.00	800.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	80.00	0.00
4	TO SUPPLY UNDER COATING / PUTTY ON PARTS REPLACED	New	80.00	0.00
5	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	80.00	0.00
6	DISMANTLE AND TRANSFER BOOT LID FITTINGS AND MECHANISM TO NEW BOOT LID / FACILITATE REPAIR	New	120.00	80.00
7	DISCONNED AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKET	New	80.00	0.00
8	REMOVE AND REPLACE REVERSE SENSOR	New	80.00	60.00
9	REMOVE AND REFIT REAR END PANEL LINING AND GARNISH TO FACILITATE REPAIR	New	80.00	0.00
10	REMOVE AND REPLACE EXHAUST MUFFLER	New	150.00	80.00
11	PROGRAMMING RADAR SYSTEM WITH DIAGNOSTIC FAULT	New	350.00	250.00
12	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTION REPAIR PARTS, INCLUSIVE OF REPLACEMENT PARTS	New	200.00	200.00
13	TO PUTTY AND SPRAY PAINT ON ALL ACCIDENT DAMAGE PARTS AND OTHER ACCIDENT	New	300.00	200.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,800.00</b>	<b>2,270.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >