

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21011285/AVY3E2

**Date:** 12/01/2022

### REFERENCE

|                   |            |                  |            |           |              |
|-------------------|------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | CHEN SIWEI | Policy No:       | 7210001607 |           |              |
| Date of Loss:     | 28/10/2021 | Nature of Claim: | OD         | Claim No: | 4386885307SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SMX7128P                     |             |                   |
| Make & Model:               | AUDI Q3, 1.4 TFSI (A)        | Engine No:  | CZDC18735         |
| Reg. Date:                  | 12/01/2021 (Man. Year: 2020) | Chassis No: | WAUZZZF36M1044875 |
| Colour:                     | Black                        | Odometer:   | 10049 km          |
| Engine Capacity:            | 1395 cc                      |             |                   |
| Market Value/New Car Price: | S\$175,000.00                |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |     |                         |     |                          |     |
|--------------------------|-----|-------------------------|-----|--------------------------|-----|
| General Condition:       |     | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification:    | No  | Pre-accident Condition:  |     |

### CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/65 R17  | Rear Tyre Size:  | 215/65 R17  |
| Front Left Side:  | Falken 6 mm | Rear Left Side:  | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                      | Repairer's       | Adjuster's      | Difference      | Diff %       |
|-------------------------------------|------------------|-----------------|-----------------|--------------|
| Parts                               | 7,652.00         | 3,352.16        | 4,299.84        | 56.19        |
| Miscellaneous Items                 | 0.00             | 0.00            | 0.00            |              |
| Labour                              | 7,252.00         | 3,832.00        | 3,420.00        | 47.16        |
| Paintwork Labour                    | 0.00             | 0.00            | 0.00            |              |
| Towing                              | 0.00             | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>14,904.00</b> | <b>7,184.16</b> | <b>7,719.84</b> | <b>51.80</b> |
| <b>- Excess (S\$)</b>               | <b>800.00</b>    | <b>800.00</b>   | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>14,104.00</b> | <b>6,384.16</b> | <b>7,719.84</b> | <b>54.74</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>987.28</b>    | <b>446.89</b>   | <b>540.39</b>   | <b>54.74</b> |
| <b>Nett Amount (S\$)</b>            | <b>15,091.28</b> | <b>6,831.05</b> | <b>8,260.23</b> | <b>54.74</b> |

### INSPECTION

|                             |            |               |  |
|-----------------------------|------------|---------------|--|
| Date of Assignment:         | 05/11/2021 |               |  |
| Date Inspected:             | 03/11/2021 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |
| Estimated Period of Repair: | 5.0 days   |               |  |

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No.                          | Qty | Part No. | Particulars                      | Condition                   | Repairer's        | Amount            |
|------------------------------|-----|----------|----------------------------------|-----------------------------|-------------------|-------------------|
| 1                            | 1   |          | *REAR BUMPER                     | Repair                      | 1,634.00 FS       | *- FS             |
| 2                            | 1   |          | *REAR BUMPER FIXING PARTS        | Not Necessary               | 211.00 FS         | *- FS             |
| 3                            | 1   |          | *REAR BUMPER SPOILER             | Not Necessary               | 459.00 FS         | *- FS             |
| 4                            | 1   |          | *REAR BUMPER BRACKET             | Not Necessary               | 48.00 FS          | *- FS             |
| 5                            | 1   |          | *REAR LIGHT REFLECTOR - LH       | Not Necessary               | 41.00 FS          | *- FS             |
| 6                            | 1   |          | *REAR BUMPER GUIDE SECTION - LH  | Not Necessary               | 63.00 FS          | *- FS             |
| 7                            | 2   |          | *REAR WHEEL ARCH COVER - LH / RH | N/S Missing / O/S Necessary | 536.00 FS         | *428.80 FS        |
| 8                            | 1   |          | *REAR DOOR - LH                  | Dented                      | 2,909.00 FS       | *2,327.20 FS      |
| 9                            | 1   |          | *REAR OUTER DOOR SEAL - LH       | Necessary                   | 135.00 FS         | *108.00 FS        |
| 10                           | 1   |          | *REAR DOOR ATTACHEMENT PART      | Not Necessary               | 311.00 FS         | *- FS             |
| 11                           | 1   |          | *REAR DOOR CATCH                 | Not Necessary               | 120.00 FS         | *- FS             |
| 12                           | 1   |          | *SILL PANEL SEAL - LH            | Not Necessary               | 135.00 FS         | *- FS             |
| 13                           | 1   |          | *DOOR COVER - LH                 | Necessary                   | 257.00 FS         | *205.20 FS        |
| 14                           | 1   |          | *REAR DOOR HANDLE - LH           | Cut                         | 198.00 FS         | *158.00 FS        |
| 15                           | 1   |          | *HOUSING PRIMED - LH             | Cut                         | 27.00 FS          | *21.60 FS         |
| 16                           | 1   |          | *SIDE MEMBER TRIM - LH           | Not Necessary               | 179.00 FS         | *- FS             |
| 17                           | 1   |          | *REAR WHEEL SPOILER - LH         | Not Necessary               | 39.00 FS          | *- FS             |
| 18                           | 1   |          | *SUNDRIES                        | Necessary                   | 350.00 FS         | *103.36 FS        |
| F=Franchise part. S=SpcNett. |     |          |                                  |                             |                   |                   |
|                              |     |          |                                  |                             | Total Parts (S\$) | 7,652.00 3,352.16 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's      | Amount          |
|---------------------------------|---|----------|-----------------|-----------------|
| <b>Labour Items</b>             |   |          |                 |                 |
| 1                               | TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION   | New      | 360.00          | 360.00          |
| 2                               | TO REMOVED AND TRANSFER LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. REINSTALL ALL PARTS REMOVED  | New      | 400.00          | 280.00          |
| 3                               | TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 2,800.00        | 1,250.00        |
| 4                               | TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR AND DOOR HANDLE  | New      | 3,500.00        | 1,750.00        |
| 5                               | TO CARRY OUT DIAGNOSTIC CHECK   | New      | 192.00          | 192.00          |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>7,252.00</b> | <b>3,832.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >