LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way, #09-16

Our File No: CC3/AIG21011286/ATY3E2

Singapore 079120 **Date:** 21/01/2022

REFERENCE

Insured/Claimant: DUBEY ADITYA Policy No: 2070179197

Date of Loss: 31/10/2021 Nature of Claim: OD Claim No: 4817949246SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMX1823E

Make & Model: AUDI Q3 SPORTBACK, 1.4 TFSI S TRONIC (17) (A) Engine No: CZDC21236

Reg. Date: 29/12/2020 (Man. Year: 2020) Chassis No: WAUZZZF33M1049810

Colour: Black Odometer: 8430 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$155,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R17 Rear Tyre Size: 215/65 R17
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm
Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,183.00	5,518.08	2,664.92	32.57
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,492.00	4,302.00	4,190.00	49.34
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	16,675.00	9,820.08	6,854.92	41.11
	- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	15,875.00	9,020.08	6,854.92	43.18
	+ GST 7.00/7.00% (S\$)	1,111.25	631.41	479.84	43.18
	Nett Amount (S\$)	16,986.25	9,651.49	7,334.76	43.18

INSPECTION

Date of Assignment: 05/11/2021

Date Inspected: Premium Automobiles Pte Ltd (UBI)

Date Inspected: 02/11/2021 Inspected At: 55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Buckled	2,805.00 FS	*2,244.00 FS
2	1		*FRONT DOOR OUTER DOOR SEAL LH	Necessary	166.00 FS	*132.80 FS
3	1		*FRON DOOR CATCH	Damaged	120.00 FS	*96.00 FS
4	1		*FRONT DOOR COVER LH	Necessary	268.00 FS	*214.40 FS
5	1		*REAR DOOR LH	Buckled	2,909.00 FS	*2,327.20 FS
6	1		*REAR DOOR ATTACHMENTS PARTS	Not Necessary	311.00 FS	*-FS
7	1		*REAR DOOR CATCH	Damaged	120.00 FS	*96.00 FS
8	1		*REAR DOOR INNER SEAL	Not Necessary	191.00 FS	*-FS
9	1		*SEAL FOR SILL PANEL LH	Not Necessary	135.00 FS	*- FS
10	1		*REAR DOOR HINGE HALF UPPER PART LH	Damaged	47.00 FS	*37.60 FS
11	1		*REAR DOOR HINGE HALF LOWER PART	Damaged	44.00 FS	*34.48 FS
12	1		*REAR DOOR COVER LH	Necessary	257.00 FS	*205.20 FS
13	1		*REAR WHEEL COVER LH	Not Necessary	268.00 FS	*- FS
14	1		*SUNDRIES	Necessary	250.00 FS	*22.40 FS
15	1		*REAR DOOR OUTER SEAL LH	Necessary	135.00 FS	*108.00 FS
16	1		*FRONT DOOR ATTACHEMENTS PARTS	Not Necessary	157.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett.	Total Parts (S\$)	8,183.00	5,518.08
				-		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	800.00	560.00
2	TO REMOVE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
3	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS REAR FENDER AND DOOR HINGES	New	3,500.00	1,750.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
5	TO REPAIR LHS B-PILLAR (Supplementary)	New	800.00	250.00
6	TO RESPRAY LHS B-PILLAR (Supplementary)	New	800.00	550.00
	Gross Labour	Cost (S\$)	8,492.00	4,302.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >