

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB21011287/UGS3Q2
Date: 18/11/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D21MFL0000447
Claimant Vehicle No :	GBJ7454B	Insured Vehicle No :	SLQ8340J
Date of Loss:	20/09/2021	Nature of Claim:	TP
		Claim No:	MFL2021D0004108

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ7454B		
Make & Model:	NISSAN NV350, 2.5 PANEL VAN 5AT 5DR (A)	Engine No:	YD25054869B
Reg. Date:	29/07/2019 (Man. Year: 2019)	Chassis No:	JN1MC2E26Z0031490
Colour:	White	Odometer:	60092 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,126.12	1,980.13	1,145.99	36.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,315.00	720.00	595.00	45.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,441.12	2,700.13	1,740.99	39.20
+ GST 7.00/7.00% (S\$)	310.88	189.01	121.87	39.20

Nett Amount (S\$)	4,752.00	2,889.14	1,862.86	39.20
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 05/11/2021

Date Inspected: 05/11/2021

Estimated Period of Repair: 3.0 days

Inspected At: Ethoz Group Ltd - Tampines (HQ)
22 TAMPINES STREET 92
Singapore 528876

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 18 Nov 2021)	
Parts:	N/A	NISSAN NV350 2.5 PANEL VAN 5AT 5DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ7454B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deep Cut	571.90 FN	*571.90 FN
2	10		*FRONT BUMPER CLIP	Necessary	50.00 FN	*30.00 FN
3	1		*FRONT BUMPER RETAINER LH	Broken	164.80 FN	*164.80 FN
4	1		*FRONT BUMPER GRILLE	Not Necessary	940.00 FN	*- FN
5	1		*HEADLAMP (LH)	Cracked	464.90 FN	*441.40 FN
6	1		*FOG LAMP COVER	Serviceable	117.90 FN	*- FN
7	1		*SIDE STEP LH	Repair	65.80 FN	*- FN
8	1		*LEFT HAND DOOR (NPA)	Repair	0.00 FN	*- FN
9	1		*COMPANY DETAILS STICKER	Necessary	20.00 FS	*20.00 FS
10	1		*ADVERTISEMENT STICKER -FRONT LH DOOR	Necessary	150.00 FS	*100.00 FS
11	1		*A/T OIL COOLER	Dented / Punctured	750.00 FN	*716.10 FN
12	1		*A/T OIL COOLER GARNISH COVER	Broken	131.50 FN	*131.50 FN
13	1		*AUTO TRANSMISSION OIL -1L	Necessary	25.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,451.80	2,185.70
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	325.68	205.57
Total Parts (\$\$)	3,126.12	1,980.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO FACILITATE REPAIR	New	600.00	300.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	600.00	400.00
3	TO APPLY ANTI RUST COATING	New	80.00	0.00
4	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	New	35.00	20.00
Gross Labour Cost (\$\$)			1,315.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >