

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/CTI21008699/GVCN2-1**Date:** 24/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00013572005	
Claimant Vehicle No :	GBG1660C	Insured Vehicle No :	PA7160E	
Date of Loss:	16/08/2021	Nature of Claim:	TP	Claim No: SNM21D204553/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG1660C		Engine No:	K9KC400D056799
Make & Model:	NISSAN NV200, 1.5 (A)		Chassis No:	VSKYBAM20Z0144521
Reg. Date:	21/06/2017 (Man. Year: 2016)		Odometer:	86472 km
Colour:	Silver			
Engine Capacity:	1461 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70R14	Rear Tyre Size:	175/70R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,139.40	2,783.79	4,355.61	61.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	830.00	2,350.00	73.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,319.40	3,613.79	6,705.61	64.98
Approved Total (Overridden) (\$\$)		2,900.00		
Nett Amount (\$\$)	10,319.40	2,900.00	7,419.40	71.90

INSPECTION

Date of Assignment:	19/08/2021	
Date Inspected:	19/08/2021	Inspected At: SPEEDWERKZ PTE LTD (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre Singapore 147807
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 24 Nov 2021)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBG1660C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut/Distorted	785.20 F	*674.50 FL
2	2		*FRONT BUMPER BRACKET	Serviceable	290.40 F	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	130.80 F	*70.40 FL
4	1		*FRONT BUMPER BEAM	Serviceable	196.40 F	*- FL
5	2		*FRONT BUMPER FOG LAMP	Cut/Cracked	391.20 F	*391.20 FL
6	1		*FRONT BUMPER SPONGE	Cracked	198.40 F	*198.40 FL
7	1		*FRONT BUMPER REINFORCEMENT	Serviceable	591.90 F	*- FL
8	1		*FRONT GRILLE	Cracked	368.90 F	*368.90 FL
9	1		*FRONT GRILLE LOGO	Cracked	78.20 F	*59.70 FL
10	2		*HEADLAMP ASSY	Cracked	1,391.60 F	*1,230.00 FL
11	2		*HEADLAMP LOWER BRACKET	Serviceable	230.80 F	*- FL
12	2		*HEADLAMP APRON GARNISH	Serviceable	697.20 F	*- FL
13	1		*BONNET	Repair	820.40 F	*- FL
14	1		*BONNET LOCK	Serviceable	197.80 F	*- FL
15	1		*FRONT SUPPORT TOP PANEL	Serviceable	395.20 F	*- FL
16	1		*SUNDRIES	Serviceable	50.00 FS	*- FS
17	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
18	1		*SET FRONT GRILLE CLIPS	Necessary	45.00 FS	*20.00 FS
19	1		*RADIATOR COOLANT	Serviceable	120.00 FS	*- FS
20	1		*FRONT NUMBER PLATE W/GARNISH	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,139.40	3,083.10
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	299.31
Total Parts (\$)	7,139.40	2,783.79

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE/RENEW THE ACCIDENT DAMAGED PORTION.TO PANEL BEATING,RESHAPE,STRAIGHTEN,ORIENTATE AND ALIGN REPAIR/REPLACEMENT PARTS	New	1,400.00	400.00
2	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS,RECONNECT AND CHECK FUNCTIONS	New	80.00	30.00
3	TO REMOVE AND REFIT A/C CONDENSER TO FACILITATE REPAIR.TO CONFIRM ON THE A/C TEMPERATURE	New	200.00	0.00
4	TO REMOVE AND REFIT RADIATOR TO FACILITATE REPAIR TO PERFORM PRESSURE TEST AND CONFIRM ON THE COOLING SYSTEM	New	200.00	0.00
5	TO APPLY UNDERCOATING ON THE ACCIDENT REPAIR AND REPLACED PANEL FOR RUST PROTECTION	New	100.00	0.00
6	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY HEADLAMP APRON GARNISHS,FRONT GRILLE,BONNET,FRONT SUPPORT TOP PANEL AND OTHER AFFECTED AREA/PANEL	New	1,200.00	400.00
Gross Labour Cost (\$\$)			3,180.00	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >