



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 3005P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BONNET	TO REPAIR SEE LABOUR	854.10	-
1	FRONT BONNET HINGE LH	TO REPAIR SEE LABOUR	53.50	-
1	FRONT BONNET HINGE RH	TO REPAIR SEE LABOUR	53.50	-
1	FRONT GRILLE OUTER GARNISH (CHROME)	CUT / SCRATCHED	437.60	437.60
1	FRONT GRILLE	CRACKED	374.70	374.70
1	FRONT GRILLE OUTER CHROME MOULDING LH	SCRATCHED	53.80	53.80
1	FRONT BUMPER	BENT	751.40	751.40
1	FRONT BUMPER SIDE BRACKET LH	DISTORTED	23.90	23.90
1	FRONT BUMPER LOWER LIP	MTG CRACKED	421.80	421.80
1	FRONT BUMPER LOWER GRILLE	SERVICEABLE	84.20	-
1	FRONT BUMPER FOG LAMP LH	MTG DENTED	626.10	327.70
1	FRONT BUMPER FOG LAMP GARNISH COVER LH	DENTED / CUT	65.10	65.10
1	FRONT BUMPER REINFORCEMENT	BENT	294.70	294.70
1	FRONT HEADLAMP LH	MTG BROKEN	1,996.30	1,865.00
1	FRONT HEADLAMP LOWER BRACKET LH	CRACKED	34.20	34.20
1	FRONT FENDER LH	BENT	421.10	421.10
1	FRONT FENDER "HYBRID" EMBLEM LH	NECESSARY	65.50	65.50
1	FRONT FENDER INNER SHIELD LH	DISTORTED	125.90	125.90
1	FRONT WHEEL ARCH GARNISH COVER LH	BUCKLED	178.90	178.90
1	FRONT DOOR LH (NPA)	TO REPAIR SEE LABOUR	-	-
1	RESONATOR	CRACKED	140.00	140.00
1	SIDE PANEL LH	TO REPAIR SEE LABOUR	110.00	-
1	WHEEL ARCH LH	REPEATED	215.00	-
	LESS 20% DISCOUNT		-1,476.26	-1,116.26
			5,905.04	4,465.04
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00

Report Ref No. CS/SMR21011289/Kuf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT FENDER INNER SHIELD CLIPS LH (SN)	NECESSARY	40.00	40.00
1	FRONT WHEEL ARCH LH CLIPS (SN)	NECESSARY	40.00	40.00
			130.00	130.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF FRONT BONNET, FRONT BONNET HINGE LH, FRONT BONNET HINGE RH, FRONT DOOR LH AND SIDE PANEL LH.		1,000.00	500.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT BUMPER LOWER LIP, FRONT FENDER LH, FRONT WHEEL ARCH COVER LH & ETC.		1,000.00	600.00
	TO DIAGNOSIS FAULT CODE & RESET MEMORY.	NOT NECESSARY	120.00	-
	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.		80.00	20.00
			2,200.00	1,120.00
GRAND TOTAL			8,235.04	5,715.04
RECOMMENDED COST OF REPAIRS				5,715.04

Report Ref No. CS/SMR21011289/Kuf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.