

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 7644S

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | REAR BUMPER | DEFORMED | 1,676.00 | 1,676.00 |
| 2 | REAR BUMPER SIDE HOLDER @\$78.00 | NECESSARY | 156.00 | 156.00 |
| 1 | REAR BUMPER LOWER GARNISH | CUT | 369.00 | 369.00 |
| 1 | REAR BUMPER LOWER GARNISH CHROME MOULDING | CUT | 258.00 | 258.00 |
| 2 | REAR BUMPER SIDE CHROME TRIM @\$137.00 | NECESSARY | 274.00 | 274.00 |
| 1 | REAR BUMPER REINFORCEMENT | DENTED | 762.00 | 762.00 |
| 2 | REAR BUMPER EXHAUST CHROME @\$266.00 | NOT NECESSARY | 532.00 | - |
| 1 | REAR BUMPER KICK SENSOR BRACKET | CRACKED | 102.00 | 102.00 |
| 2 | REAR BUMPER BRACKET @\$45.00 | O/S CRACKED | 90.00 | 45.00 |
| 14 | REVERSE SENSOR @\$260.00 | DAMAGED (2 PCS ONLY) | 1,040.00 | 520.00 |
| 1 | REAR END PANEL | TO REPAIR SEE LABOUR | 1,215.00 | - |
| 1 | REAR END PANEL TOP GARNISH | NOT NECESSARY | 241.00 | - |
| 2 | TAILLAMP @\$685.00 | NOT NECESSARY | 1,370.00 | - |
| 1 | MERCEDES BENZ LOGO | NECESSARY | 75.00 | 75.00 |
| 1 | E200 EMBLEM | NECESSARY | 65.00 | 65.00 |
| 1 | CYCLE AND CARRIAGE LOGO | NECESSARY | 38.00 | 38.00 |
| | LESS 10% DISCOUNT | | - | -434.00 |
| | | | 8,263.00 | 3,906.00 |
| | SPECIAL NETT ITEMS | | | |
| 1 | REAR END PANEL SEALANT (SN) | NOT NECESSARY | 60.00 | - |
| 1 | REAR BUMPER CLIPS (SN) | NECESSARY | 50.00 | 50.00 |
| | | | 110.00 | 50.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL. | | 1,000.00 | 450.00 |
| | SPRAY PAINTING. | | 1,000.00 | 450.00 |
| | WIRING. | | 50.00 | 30.00 |
| | TO REMOVE REVERSE SENSOR. | | 100.00 | 50.00 |
| | TO REMOVE UPHOLSTERY. | | 150.00 | 40.00 |

Report Ref No. CS/SMR21011295/Atf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|----------------------|-----------|-------------------------------|-------------------|
| | TO SPRAY TUFF COAT. | | 150.00 | 40.00 |
| | | | 2,450.00 | 1,060.00 |
| | GRAND TOTAL | | 10,823.00 | 5,016.00 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 4,000.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CS/SMR21011295/Atf3n2



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.