

TP SMRT.

Hui Zhen.

SKN 76445 2014 July.

Mercedes Benz F200 1991cc.

WDD2120342 B003480.

Rear Bumper	Dented	1676	✓
Rear Bumper Clips	Nu	50(SN)	✓
Rear Bumper Side Holder x 02	MP nec	$78 \times 2 = 156$	✓
Rear Bumper Lower Garnish.	cut	369.	✓
Rear Bumper Lower Garnish Chrome Moulding	cut	258	✓
Rear Bumper Side Chrome Trim x 02	MP	$137 \times 2 = 274$	✓
Rear Bumper Reinforcement.	Dented	762	✓
Rear Bumper Exhaust Chrome x 02	MP nu	$266 \times 2 = 532$	+
Rear Bumper Kick Sensor Bracket	Quel	102	✓
Rear Bumper Bracket x 02	RH Quel	$45 \times 2 = 90$	45
Reverse Sensor x 04	2 pieces damaged	$260 \times 4 = 1040$	520
Rear End Panel	Repair	1215	+
Rear End Panel Top Garnish?	MP	241	+
Rear End Panel Sealant	MP	60(SN)	+
Taillamp x 02	Xben	$685 \times 2 = 1370$	+

SKN 76445.

Mercedes Benz Logo

E 200 Emblem

Cycle and Carriage Logo.

} New

75 ✓

65 ✓

38 ✓

4518

S-N: 50

4066.20

Panel Beating

Spray Painting.

Wiring.

To remove reverse sensor

To remove upholstery,

To spray tuff coat

~~1000~~ 400 450

~~1000~~ 400 450

~~50~~ 30 ✓

~~100~~ 50

~~150~~ 40

~~150~~ 40

960

Total: 5076.20

h/s: AK

03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

✓

10823