

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: S9M01Q0F Date: 16th Nov 2021

Our Ref: CS3/ASM19010364/R1vy3e2-1

M/s Axa Insurance Pte Ltd

8 Shenton Way #24-01 Axa Tower Singapore 068811 (The Motor Claims Department)

Attn: Lynn Khong

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLA 8549J INSURED VEHICLE: SJU 9699X ACCIDENT DATE: 08/06/2019

We thank you for your instruction on 05/11/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLA 8549J from M/s C L Appraiser Pte Ltd.
- b) Singapore Accident Statement of Vehicles SLA 8549J and SJU 9699X.
- c) Final Repair Bill of SLA 8549J from M/s TeamWork Garage Pte Ltd.
- d) Colour damaged vehicle photographs of SLA 8549J.

Pre-Repair Inspection Date: 12/06/2019 at M/s TeamWork Garage Pte Ltd, 53 Ubi Avenue 1 #01-24, Singapore 408934.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SLA 8549J Make & Model : Toyota Estima

Year of Registration : -

Chassis Number : ACR500116793

Engine Capacity : 2362 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.