

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |  |                |       |                        |  |
|---|--|--|----------------|-------|------------------------|--|
|   | AXA INSURANCE I  | PTE LTD  |                | Ref:  | CC4/ASM21011302/Aps3q2 |  |
|   | 8 SHENTON WAY<br>AXA TOWERSING   |  |                | Date: | 24/12/2021             |  |
|   | ATTN:VALE OH   |  |                | Code: | ASM                    |  |
| 1.  | 1. Policy Particulars :- THIRD PARTY CLAIM   |  |                |       |                        |  |
|   | Insured Veh.   | SHC 1770T  | Veh. Inspected | l     | SMS 3486H              |  |
|   | Policy No.   | P2419138   | Coverage (\$)  |       | 0.00                   |  |
|   | Claim No.  | S1M03LAN   | Excess (\$)    |       | 0.00                   |  |
|   | Assign From  |  | Assign Date    |       | 05/11/2021             |  |
| 2. Vehicle Particulars & Condition                                |  |  |                |       |                        |  |
|   | Make & Model   | TOYOTA ALTIS   | c.c            |       | 1598                   |  |
|   | Engine No.   | HIDDEN   | Year of Reg.   |       | 2020                   |  |
|   | Chassis No.  | MR2BE3BE100008086  | Colour         |       | BLACK                  |  |
|   | Odometer   | 16074 KM   | Steering       |       | IN ORDER               |  |
|   | Brakes   | IN ORDER   | Modification   |       | SPORTS RIM             |  |
|   | General  | GOOD   |                |       |                        |  |
| 3. Conditions of Tyres  |  |  |                |       |                        |  |
|   |  | Size   | Make           |       | Balance                |  |
|   | R/H Front Tyre   | 225/45 R17   | DUNLOP         |       | 6 mm                   |  |
|   | L/H Front Tyre   | 225/45 R17   | DUNLOP         |       | 6 mm                   |  |
|   | R/H Rear Tyre  | 225/45 R17   | DUNLOP         |       | 6 mm                   |  |
|   | L/H Rear Tyre  | 225/45 R17   | DUNLOP         |       | 6 mm                   |  |
| 4.  |  |  |                |       |                        |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  |  |                |       |                        |  |
|   | DAMAGES SEE DETAILS.   |  |                |       |                        |  |
| 5.  | General Information  |  |                |       |                        |  |
|   | Accident Date  | 01/11/2021   | Inspection Dat | е     | 05/11/2021             |  |
|   | Survey held at   | LIANG HEE MOTOR WORKSHO                                  | )P             |       |                        |  |
|   |  | 1 KAKI BUKIT AVE 6<br>#01-62 AUTOBAY<br>SINGAPORE 417883 |                |       |                        |  |
| 5a.   | Remarks  |  |                |       |                        |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                |       |                        |  |
| 5b.   | Estimate Days of Repair  |  |                |       |                        |  |
|   | STIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days  |  |                |       |                        |  |
|   | <u> </u>   |  |                |       |                        |  |