

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE		Ref:	CS3/ASM21011305/T1ty3e2	
	8 SHENTON WAY SINGAPORE 0688		Date:	15/11/2021	
	ATTN: ANG YVON	NE		Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHA 7007K	Veh. Inspected	ł	FBK 2734X
	Policy No.	VFX/P2419138	Coverage (\$)		0.00
	Claim No.	S1M03JX4	Excess (\$)		0.00
	Assign From	ANG YVONNE	Assign Date		05/11/2021
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA CB400SF	c.c		399
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	NC421603109	Colour		RED
	Odometer	-	Steering		IN ORDER
	Brakes	IN ORDER	Modification		NIL
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	120/60 R17	CONTINENTAL		5 mm
	L/H Front Tyre				mm
	R/H Rear Tyre	160/60 R17	CONTINENTAL		5 mm
	L/H Rear Tyre				mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT PORTION.				
5.	General Information				
	Accident Date	13/10/2021	Inspect Date /	Time	08/11/2021 (02:20 PM)
	Survey held at WING FUAT TRADING CO BLK 3020A UBI ROAD 1 #01-37 SINGAPORE 408714				
5a.	a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$7,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days				

Report Ref No. CS3/ASM21011305/T1ty3e2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser