

08/11/13; wef

ASS. REC. BY: *Marcus*

REF:

CS/CT121011307/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD *(B)* / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLQ 75862

at Workshop m/s

Siang hai

of

Insured:

GSF 7100T

Policy No.

Claims No.

SNM21D206246/C02

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

88k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6242

Vehicle: IN / OUT

Date:

Person Contacted:

LTA 45361

Veh No:

SLQ 75862 Yr Regn: *21/7/17*Type: *M*.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A) premium

Make:

Toyota harrier

C.C

1986

Colour

pearl white

A/C:

Insured / Std / NI / NA

Sp. Reading

*116286*T/Radio: *Insured / Std / NI / NA*

Eng/No:

C/No:

2SU 600081006

Gen. Cond:

*Good / Fair / Poor / Burnt*Steering: *In order* / Jammed / Leaked / Burnt or

Brake:

In order / Jammed / Leaked / Burnt or

Modi:

Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/50 R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

11/11/12

D.O.I.

10/11/12

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Rep 13k**for hwy 811.30 kit 1500**13/11/12 4/5 \$4100 confirmed with AH hai: (Red \$3969.52, 49%)*

15/11/21@1.03pm revised to Adeline Chng via Merimen.

Date/Time, File Pass to?

☐

Preli. Report

1) 15/11 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format: MER-TP

Lump Sum *4100* (\$) 4100

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

祥輝汽車修理 SIANG HUI MOTOR WORKS

Blk 3006, Ubi Road 1 #01-338, Singapore 408700.

Tel: 67444605 Fax: 67440726

REG. No. 322208/00M

not Admitted
10/11/21

1/5 \$4100 3 days

Date, 6/11/21

Vehicle No: SLQ 7586 Z

1	1pc Front bumper	re/wash	\$622.10	✓
2	1pc Front bumper side retainer	cro	\$115.20	✓
3	1pc Fog light o/s	nn	\$308.80	X
4	1pc Fog light cover o/s	nn	\$165.70	X
5	1pc Front bumper lower lip	replace	\$1350.70	✓
6	1pc Front bumper lower grille	nn	\$483.70	X
7	1pc Headlamp o/s	3301 holder cro	\$3478.10	✓
8	1pc Headlamp lower bracket o/s	sent	\$117.40	69.80 ✓
9	1pc Headlamp lower bracket sponge	o/s	\$45.30	✓
10	1pc Bumper sensor	nn	\$278.60	X
11	1pc Front fender o/s	R	\$1446.30	X
			\$8411.90	
Less 20% GST			\$6729.52	

Labour charges:-

1	To remove, replace sensor & check wiring	\$80.00	50
2	To spray painting	\$680.00	600
3	To remove, replace, headlamp bumper & fender	\$580.00	400
Total:-		\$8069.52	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5304.1

252

P-4128.07

2-1050

5178.27

20%
1035.65