

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Page No.:1 of 1

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL CS3/SMO21011310/Kuf3e2 Ref: 50 RAFFLES PLACE #03-03 Date: 12/11/2021 SINGAPORE LAND TOWERSINGAPORE 048623 Code: SMO 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SBT 7003S** SMS 5845S Veh. Inspected Policy No. D21MTPV01004267 Coverage (\$) 0.00 Claim No. CMTD2103186/GPL Excess (\$) 0.00 **GRACE TEO Assign Date** 05/11/2021 Assign From **Vehicle Particulars & Condition** 2. TOYOTA ESTIMA (A) Make & Model 2362 C.C HIDDEN 2015 Engine No. Year of Reg. ACR500191986 WHITE Chassis No. Colour Odometer 105156 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 225/50 R18 FALKEN 3 mm **FALKEN** L/H Front Tyre 225/50 R18 3 mm 225/50 R18 **FALKEN** R/H Rear Tyre 4 mm FALKEN 4 mm L/H Rear Tyre 225/50 R18 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR BODY. 5. **General Information** 23/10/2021 08/11/2021 ( 02:30 PM ) **Accident Date** Inspect Date / Time **NEXWAVE AUTO** Survey held at 160 SIN MING DRIVE #05-15 SIN MING AUTOCITY SINGAPORE 575722 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Report Ref No. CS3/SMO21011310/Kuf3e2

D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

**Estimate Days of Repair** 

Inspected By

5b.

KONG SENG CHEONG

**Licensed Appraiser** 

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

3 Working Days

REGD Auto Consultant-SAE, Licensed Appraiser