

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG21011319/APA3Q2**Date:** 29/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210127961
<b>Claimant Vehicle No :</b>	SGZ9359L	<b>Insured Vehicle No :</b>	SKE4315J
Date of Loss:	04/11/2021	Nature of Claim:	TP
		Claim No:	1320639661SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SGZ9359L</b>	Engine No:	DEM025429
Make & Model:	AUDI A4, 2.0 TFSI S-TRONIC (A)	Chassis No:	WAUZZZF40MN000954
Reg. Date:	29/12/2020 (Man. Year: 2020)	Odometer:	29723 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R19	Rear Tyre Size:	245/40 R19
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,140.00	6,881.28	12,258.72	64.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	16,872.00	9,997.00	6,875.00	40.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>36,012.00</b>	<b>16,878.28</b>	<b>19,133.72</b>	<b>53.13</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	2,520.84	1,181.48	1,339.36	53.13
<b>Nett Amount (\$\$)</b>	<b>38,532.84</b>	<b>18,059.76</b>	<b>20,473.08</b>	<b>53.13</b>
<b>+ Car Rental (15.0 x S\$150.00/day) (\$\$)</b>		2,250.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>20,311.76</b>		

INSPECTION

Date of Assignment:	05/11/2021		
Date Inspected:	09/11/2021	Inspected At:	Premium Automobiles Pte Ltd (HQ) 55 UBI ROAD 1 Singapore 408699
Estimated Period of Repair:	13.0 days		

**Adjuster:** ADRIAN LING**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	2,342.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	166.00 FS	*- FS
3	2		*REAR BUMPER TOP GUIDE SECTION-LH/RH	Not Necessary	46.00 FS	*- FS
4	1		*REAR BUMPER GUIDE SECTION -LH	Not Necessary	44.00 FS	*- FS
5	1		*REAR SECTIONAL PARTS -LH	Dented	4,052.00 FS	*3,241.60 FS
6	1		*REAR WINDSCREEN	Necessary	1,154.00 FS	*923.20 FS
7	1		*REAR 1/4 GLASS	Necessary	656.00 FS	*524.40 FS
8	2		*PRIMER	Necessary	40.00 FS	*31.52 FS
9	1		*REAR WHEEL HOUSING LINER -LH	Not Necessary	240.00 FS	*- FS
10	1		*REAR SUB FRAME	Not Necessary	3,286.00 FS	*- FS
11	1		*REAR WISHBONE-LOWER	Not Necessary	859.00 FS	*- FS
12	1		*REAR WISHBONE-LH UPPER	Not Necessary	556.00 FS	*- FS
13	1		*REAR WISHBONE-LH FRONT	Not Necessary	123.00 FS	*- FS
14	1		*REAR WISHBONE -LH REAR	Not Necessary	447.00 FS	*- FS
15	1		*REAR TRACK ROD -LH REAR	Not Necessary	171.00 FS	*- FS
16	1		*REAR WHEEL BEARING HOUSING -LH	Not Necessary	990.00 FS	*- FS
17	1		*REAR WHEEL BEARING -LH	Not Necessary	654.00 FS	*- FS
18	1		*STONE CHIP GUARD	Not Necessary	45.00 FS	*- FS
19	1		*REAR ABSORBER -LH	Not Necessary	301.00 FS	*- FS
20	1		*REAR COUPLING ROD	Not Necessary	86.00 FS	*- FS
21	1		*REAR ANTI ROLL BAR	Not Necessary	412.00 FS	*- FS
22	1		*1/4 GLASS	Necessary	100.00 FS	*100.00 FS
23	1		*CRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
24	1		*CRAVITY WAX	Necessary	140.00 FS	*140.00 FS
25	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
26	1		*METAL FILLER POWER	Necessary	280.00 FS	*280.00 FS
27	1		*REAR WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
28	1		*REAR RIM -LH	Cut	700.00 FS	*700.00 FS
29	1		*REAR TYRE RIM -LH	Cut	340.00 FS	*340.00 FS
30	1		*SUNDRIES	Necessary	350.00 FS	*40.56 FS

F=Franchise part. S=SpcNett.

**Total Parts (S\$)**      **19,140.00**      **6,881.28**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REINSTALL REAR PARKING AID REAR LID KICK SENSOR	New	360.00	360.00
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL	New	600.00	600.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS SIDE 1/4 GLASS	New	400.00	180.00
4	TO CARRY OUT WARE SEEPAGE TEST ON 1/4 GLASS	New	200.00	150.00
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY	New	1,400.00	1,400.00
6	TO REMOVE AND REINSTALL REAR SEAT ,BACT REST ,HAT TRAY ,ABCD PILLAR TRIMS ,LUGGAGE COMPARTMENTS TRIMS ,DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	1,400.00
7	TO RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,400.00	0.00
8	TO DISMANTLE AND RENEW REAR BUMPER .TO CUT OUT AND WELD LHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	4,900.00	3,000.00
9	TO RESPRAY REAR BUMPER .TO CUT OUT WELD LHS REAR FENDER .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	4,500.00	2,475.00
10	TO RENEW LHS REAR RIM ,TO CARRY OUT PRE-POST WHEEL ALIGNMENT	New	520.00	240.00
11	10 CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
<b>Gross Labour Cost (\$)</b>			<b>16,872.00</b>	<b>9,997.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >