

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21011320/KGA3Q2**Date:** 31/05/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MFL0005826_01

Claimant Vehicle No : SHD158M **Insured Vehicle No :** SNA3712M

Date of Loss: 02/11/2021 Nature of Claim: TP Claim No: MFL2021D0004800

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD158M**
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C002671
 Reg. Date: 04/09/2015 (Man. Year: 2015) Chassis No: VF1ABL15AUC282265
 Colour: Metallic White/Red Odometer: 617735 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 8 mm
 Front Right Side: Sailun 9 mm Rear Right Side: Sailun 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,415.81	2,124.63	1,291.18	37.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,580.00	950.00	6,630.00	87.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,995.81	3,074.63	7,921.18	72.04
Approved Total (Overridden) (S\$)		2,450.00		
(S\$)	10,995.81	2,450.00	8,545.81	77.72
+ GST 7.00/7.00% (S\$)	769.71	171.50	598.21	77.72
Nett Amount (S\$)	11,765.52	2,621.50	9,144.02	77.72
+ Loss of Use (4.0 x S\$40.00/day) (S\$)		160.00		
+ Car Rental (4.0 x S\$81.13/day) (S\$)		324.52		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,113.47		

INSPECTION

Date of Assignment: 05/11/2021

Date Inspected: 05/11/2021 Inspected At: Trans-cab Auto Services Pte Ltd
 No 2 Ang Mo Kio Street 63
 Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 15 Dec 2021)

Parts: 143 RENAULT LATITUDE 2.0 DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHD158M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
4	1		*BUMPER BRACKET KIT FRT RH	Distorted	101.40 FL	*101.40 FL
5	1		*HEADLAMP RH	Mtg Cracked	743.60 FL	*743.60 FL
6	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
7	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
8	1		*WHEELARCH FRT RH	Torn	191.40 FL	*191.40 FL
9	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
10	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
11	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
12	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
13	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
14	1		*BUMPER CLIP FRT	Necessary	85.00 FS	*66.00 FS
15	1		*FENDER CLIP	Not Necessary	65.00 FS	*- FS
16	1		*FENDER LINER CLIP	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,761.68	2,346.70
- List Item Discount on L Items 10.00/10.00% (\$\$)	345.87	222.07
Total Parts (\$\$)	3,415.81	2,124.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	440.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	400.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
Gross Labour Cost (\$\$)			7,580.00	950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >