

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III21011323/REA3Q2**Date:** 04/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MPC0001209\_02

**Claimant Vehicle No :** SGR6881G **Insured Vehicle No :** SLM4656X

Date of Loss: 03/11/2021 Nature of Claim: TP Claim No: MPC2021D0004822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGR6881G**

Make & Model: VOLKSWAGEN PASSAT B8, 1.8 TFSI (A) Engine No: CJS308743

Reg. Date: 27/09/2019 (Man. Year: 2019) Chassis No: WVVZZZ3CZKE125075

Colour: Black Odometer: 41090 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40 R19 Rear Tyre Size: 235/40 R19

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,518.20	2,776.57	2,741.63	49.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,840.00	3,200.00	6,640.00	67.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>15,358.20</b>	<b>5,976.57</b>	<b>9,381.63</b>	<b>61.09</b>
<b>+ GST 7.00/7.00% (S\$)</b>	1,075.07	418.36	656.71	61.09
<b>Nett Amount (S\$)</b>	<b>16,433.27</b>	<b>6,394.93</b>	<b>10,038.34</b>	<b>61.09</b>
<b>+ Car Rental (3.0 x S\$120.00/day) (S\$)</b>		360.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>6,762.38</b>		

INSPECTION

Date of Assignment: 05/11/2021

Date Inspected: 09/11/2021 Inspected At:

Volkswagen Group Singapore Pte Ltd  
247 ALEXANDRA ROAD  
Singapore 159934

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jan 2022)
<b>Parts:</b>	143	VOLKSWAGEN PASSAT B8 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SGR6881G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INSCRIPTION BRIGHT CHROME NAME PLATE -PASSAT	Not Necessary	76.27 FS	*- FS
2	1		*COVER PRIMED REAR BUMPER	Scratched	1,725.58 FS	*1,725.58 FS
3	1		*SPOILER PRIMED	Scratched	296.35 FS	*296.35 FS
4	10		*POP-RIVET	Necessary	12.30 FS	*12.30 FS
5	1		*BUMPER REINFORCEMENT	Serviceable	663.77 FS	*- FS
6	1		*ATTACHMENT STRIP BUMPER CTR BRACKET	Serviceable	63.73 FS	*- FS
7	1		*GUIDE LHR BUMPER BRACKET (UPPER)	Serviceable	23.92 FS	*- FS
8	1		*GUIDE RHR BUMPER BRACKET (UPPER)	Serviceable	23.92 FS	*- FS
9	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Serviceable	40.88 FS	*- FS
10	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Serviceable	40.88 FS	*- FS
11	1		*SET SENSOR BRACKETS	Necessary	46.02 FS	*46.02 FS
12	2		*SENSOR PRIMED	Serviceable	357.96 FS	*- FS
13	2		*SEAL RING SATIN BLACK	Not Necessary	2.64 FS	*- FS
14	1		*2K-PLASTIC ADHESIVE	Necessary	81.39 FS	*81.39 FS
15	1		*BONDING AGENT FOR PLASTIC	Necessary	65.42 FS	*65.42 FS
16	1		*DECORATIVE MOULDING BRIGHT BUMPER LOWER CHROM LH	Scratched	173.63 FS	*173.63 FS
17	1		*DECORATIVE MOULDING BRIGHT BUMPER LOWER CHROM RH	Serviceable	173.63 FS	*- FS
18	1		*DECORATIVE MOULDING BRIGHT BUMPER LOWER CHROM (CTR)	Scratched	226.18 FS	*226.18 FS
19	2		*LED LICENCE PLATE LIGHT	Serviceable	201.90 FS	*- FS
20	1		*REFLECTOR LHS REFLECTOR INNER	Scratched	69.70 FS	*69.70 FS
21	1		*REFLECTOR LHS REFLECTOR OUTER	Not Necessary	69.70 FS	*- FS
22	1		*LOCK CARRIER REAR END PANEL	Serviceable	422.98 FS	*- FS
23	1		*ZINC SPRAY	Not Necessary	69.13 FS	*- FS
24	1		*2K-BODY ADHESIVE	Not Necessary	445.77 FS	*- FS
25	1		*SEALANT CAN BE SPRAYED	Not Necessary	64.55 FS	*- FS
26	1		*REAR NUMBER PLATE	Bent	80.00 FS	*80.00 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)** **5,518.20** **2,776.57**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	5,040.00	840.00
4	SPRAY PAINT	New	3,200.00	1,600.00
5	R&R REAR LUGGAGE TRIM	New	840.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>9,840.00</b>	<b>3,200.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >