

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21011327/UQF3E2

Date: 18/11/2021

REFERENCE

Insured/Claimant: YEO HONG HONG Policy No: D19MPC0001209_02
Date of Loss: 03/11/2021 Nature of Claim: OD Claim No: MPC2021D0004822

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLM4656X**
Make & Model: HYUNDAI ELANTRA, 1.6 (A) Engine No: G4FGGU015876
Reg. Date: 31/03/2017 (Man. Year: 2016) Chassis No: KMHD841CMHU333519
Colour: Beige Odometer: 99428 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$54,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55ZR16 Rear Tyre Size: 205/55ZR16
Front Left Side: Gremax 6 mm Rear Left Side: Gremax 6 mm
Front Right Side: Gremax 6 mm Rear Right Side: Gremax 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,341.77	2,942.72	1,399.05	32.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,220.00	1,120.00	47.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,681.77	4,162.72	2,519.05	37.70
Approved Total (Overridden) (S\$)		3,300.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	6,081.77	2,700.00	3,381.77	55.61
+ GST 7.00/7.00% (S\$)	425.72	189.00	236.72	55.60
Nett Amount (S\$)	6,507.49	2,889.00	3,618.49	55.61

INSPECTION

Date of Assignment: 08/11/2021
Date Inspected: 08/11/2021 Inspected At: Precise Auto Service (HQ)
Singapore 417883
Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 10 Nov 2021)
Parts:	143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM4656X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BONNET (WCP)	Dented / Bent	520.00 F	*520.00 F
2	1	*FRONT NUMBER PLATE GARNISH (WCP)	Torn	54.10 F	*54.10 F
3	1	*BONNET LOCK MECHANISM (WCP)	Twisted	75.00 F	*75.00 F
4	1	*HEAD LAMP ASSY (WCP)	N/S NotNecessary/O/S Cracked	1,500.00 F	*750.00 F
5	1	*HEAD LAMP BRACKET (WCP)	N/S NotNecessary/O/S Cracked	46.00 F	*23.00 F
6	1	*FRONT BUMPER FASCIA (WCP)	Distorted	290.00 F	*290.00 F
7	10	*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
8	1	*FRONT BUMPER TOW COVER (WCP)	Deformed	15.00 F	*15.00 F
9	1	*FRONT BUMPER GRILLE CENTER (WCP)	Cracked	400.00 F	*400.00 F
10	1	*FRONT BUMPER SPONGE (WCP)	Torn	55.00 F	*55.00 F
11	1	*FRONT BUMPER REINFORCEMENT BEAM (WCP)	Dented	265.00 F	*265.00 F
12	2	*FRONT BUMPER BRACKET (WCP)	Not Necessary	44.00 F	*- F
13	2	*FRONT BUMPER SIDE RETAINER (WCP)	Not Necessary	50.00 F	*- F
14	1	*FRONT BUMPER TOP GARNISH COVER (WCP)	Cracked	45.00 F	*45.00 F
15	6	*FRONT BUMPER TOP GARNISH COVER CLIPS (WCP)	Necessary	12.00 F	*12.00 F
16	1	*FRONT SUPPORT PANEL (WCP)	Not Necessary	320.00 F	*- F
17	1	*FRONT NUMBER PLATE }	Bent	45.00 FS	*40.00 FS
18	1	*FRONT NUMBER PLATE CASING }		29.00 FS	*- FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	3,785.10	2,564.10
+ Margin on L,N Items 15.00/15.00% (\$\$)	556.67	378.62
Total Parts (\$\$)	4,341.77	2,942.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	100.00	0.00
2	TO CHECK WIRING SYSTEM	New	80.00	20.00
3	TO REMOVE & REFIX AIR COND CONDENSOR, VACUUM & TOP UP GAS	New	180.00	0.00
4	TO REMOVE & REFIX RADIATOR AND TOP UP COOLANT	New	180.00	0.00
5	TO RESPRAY AFFECTED AREAS	New	850.00	700.00
6	TO REPLACE DAMAGED PARTS, STRAIGHTEN, REPAIR AND ALIGNED ALL PARTS	New	950.00	500.00
Gross Labour Cost (\$\$)			2,340.00	1,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >