

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIG21011332/KUF3N2**Date:** 11/11/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000001
<b>Claimant Vehicle No :</b>	SMR1931H	<b>Insured Vehicle No :</b>	SLT9817D
Date of Loss:	27/09/2021	Nature of Claim:	TP
		Claim No:	6910362385SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SMR1931H</b>		
Make & Model:	TOYOTA NOAH, 1.8 (A)	Engine No:	2ZR2F09165
Reg. Date:	23/12/2019 (Man. Year: 2019)	Chassis No:	ZWR800410225
Colour:	Metallic Maroon	Odometer:	168696 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Farroad 8 mm	Rear Left Side:	Star 9 mm
Front Right Side:	Farroad 8 mm	Rear Right Side:	Star 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,532.35	2,251.31	1,281.04	36.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,020.00	440.00	580.00	56.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>4,552.35</b>	<b>2,691.31</b>	<b>1,861.04</b>	<b>40.88</b>

**INSPECTION**

Date of Assignment:	08/11/2021	
Date Inspected:	08/11/2021	Inspected At: BLK 5038 ANG MO KIO INDUSTRIAL PARK 2, #01-405 SINGAPORE 569541. REPAIRER: LIAN HER MOTORS
Estimated Period of Repair:	2.0 days	

**Adjuster:** KENNETH KONG**Manager:** Tan Hui Zhen

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT O/S HEADLAMP ASSY	Cut	3,203.70 FL	*3,001.75 FL
2	1		*FRONT N/S HEADLAMP GARNISH	Serviceable	155.20 FL	*- FL
3	1		*FRONT BUMPER	Repair	1,255.70 FL	*- FL
4	1		*FRONT O/S BUMPER SIDE RETAINER	Serviceable	95.20 FL	*- FL
F=Franchise part. L=ListItemDisc.						
					Sub Total (\$)	4,709.80 3,001.75
					- List Item Discount on L Items 25.00/25.00% (\$)	1,177.45 750.44
					Total Parts (\$)	3,532.35 2,251.31

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING & CUTTING	New	500.00	200.00
2	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	New	500.00	220.00
3	CHECK/RECONNECT WIRING	New	20.00	20.00
<b>Gross Labour Cost (\$)</b>			<b>1,020.00</b>	<b>440.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >