

| | | | | | | | | | | | | |
|---|---|---|--------|---|---|---|---|------|---|---|---|-------------|
| ⏪ | < | 1 | of 2 ? | > | ⏩ | ↺ | ↻ | 100% | ▼ | 📄 | 🖨 | Find Next |
|---|---|---|--------|---|---|---|---|------|---|---|---|-------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---|----------------|
| MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807 | | Ref: CS/MSG21011335/Uvf3 Date: 08/11/2021 Code: MSG | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SMK 712S | Veh. Inspected | SJR 7040A |
| Policy No. | A29142301AT2 | Coverage (\$) | 0.00 |
| Claim No. | 638717 | Excess (\$) | 0.00 |
| Assign From | CRYSTAL LEE | Assign Date | 08/11/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 05/11/2021 | Inspection Date | 08/11/2021 |
| Survey held at | at Blk 15 Kaki Bukit Road 4, Bartley Biz , #01-53 | | |
| Repairer | ZOOM AUTOWERKS PTE LTD | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |