

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21011338/UVY3N2**Date:** 30/11/2021**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00189072106	
Claimant Vehicle No :	SFK7999T	Insured Vehicle No :	SKV4857Y	
Date of Loss:	03/11/2021	Nature of Claim:	TP	Claim No: SNM21D206338/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFK7999T		Engine No:	HRA2219179A
Make & Model:	NISSAN QASHQAI, 1.2 (A)		Chassis No:	SJNFEAJ11U1549286
Reg. Date:	18/12/2015 (Man. Year: 2015)		Odometer:	39311 km
Colour:	Grey			
Engine Capacity:	1197 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,126.24	1,035.68	1,090.56	51.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	1,290.00	120.00	8.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,536.24	2,325.68	1,210.56	34.23
+ GST 7.00/7.00% (\$\$)	247.54	162.80	84.74	34.23
Nett Amount (\$\$)	3,783.78	2,488.48	1,295.30	34.23

INSPECTION

Date of Assignment:	08/11/2021		
Date Inspected:	10/11/2021	Inspected At:	Autolution Industrial Pte Ltd (Ubi) 19 Ubi Road 4 Singapore 408623
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Nov 2021)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFK7999T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOW HOOK COVER	Not Necessary	18.80 FN	*- FN
2	1		*REAR BUMPER STAY LH	Not Necessary	141.00 FN	*- FN
3	1		*REAR BUMPER STAY RH	Not Necessary	141.00 FN	*- FN
4	1		*REAR BUMPER REINFORCEMENT	Not Necessary	691.50 FN	*- FN
5	1		*REAR BUMPER SIDE BRKT LH	Not Necessary	38.90 FN	*- FN
6	1		*REAR BUMPER SIDE BRKT RH	Not Necessary	38.90 FN	*- FN
7	1		*ENERGY ABSORBER REAR BUMPER	Not Necessary	155.60 FN	*- FN
8	1		*REAR BUMPER RETAINER	Necessary	25.70 FN	*25.70 FN
9	10		*CLIP REAR BUMPER	Necessary	80.00 FN	*80.00 FN
10	1		*REAR BUMPER FASCIA	Distorted	876.40 FN	*876.40 FN
11	1		*SUNDRIES	Not Necessary	50.00 FS	*- FS
12	1		*REAR LICENCE PLATE (SCRATCHED)	Not Consistent With The Impact	60.00 FS	*- FS
13	1		*SENSOR-REVERSE	Shorted/Torn	250.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	2,567.80	1,232.10
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	441.56	196.42
Total Parts (\$\$)	2,126.24	1,035.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER	New	700.00	680.00
2	SUPPLY REAR LICENCE PLATE (NPA)	New	0.00	0.00
3	CHARGES TO SPRAY PAINTING SAME	New	600.00	500.00
4	REMOVE AND INSTALL REAR BUMPER SENSOR TO RENEW AND RESET	New	110.00	110.00
Gross Labour Cost (\$)			1,410.00	1,290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >