

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21011339/ETF3E2**Date:** 27/12/2021**REFERENCE**

Insured/Claimant: PAN PACIFIC VAN & TRUCK LEASING PTE LTD
Date of Loss: 28/10/2021

Policy No: D19MFL0005549-02
Nature of Claim: OD

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBL1932S**
 Make & Model: TOYOTA HIACE, 1.8 D SUPER GL DARK PRIME (A) Engine No: 1KDB071416
 Reg. Date: 29/03/2021 (Man. Year: 2020) Chassis No: JTFHT02PX00251605
 Colour: White Odometer: 19681 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: S\$60,000.00
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,233.50	5,166.00	3,067.50	37.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,670.00	1,430.00	2,240.00	61.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,903.50	6,596.00	5,307.50	44.59
Approved Total (Overridden) (S\$)		6,200.00		
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	10,403.50	4,700.00	5,703.50	54.82
+ GST 7.00/7.00% (S\$)	728.25	329.00	399.25	54.82
Nett Amount (S\$)	11,131.75	5,029.00	6,102.75	54.82

INSPECTION

Date of Assignment: 08/11/2021

Date Inspected: 09/11/2021 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise
Building
Singapore 508775

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Dec 2021)	
Parts:	N/A	TOYOTA HIACE 1.8 D SUPER GL DARK PRIME (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBL1932S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	190.00 F	*190.00 F
2	1		*FRONT BUMPER GRILLE	Broken	75.00 F	*75.00 F
3	2		*FRONT BUMPER SIDE RETAINER LH / RH	Broken	130.00 F	*130.00 F
4	1		*FRONT FOG LAMP COVER LH / RH	O/S Broken	100.00 F	*50.00 F
5	1		*FRONT REINFORCEMENT	Dented	100.00 F	*100.00 F
6	1		*FRONT BUMPER CENTER BEAM	Necessary	55.00 F	*55.00 F
7	1		*FRONT GRILLE TOP	Cut	100.00 F	*100.00 F
8	1		*FRONT GRILLE LOWER	Cut	120.00 F	*120.00 F
9	1		*FRONT GRILLE INNER	Broken	180.00 F	*180.00 F
10	2		*HEADLAMP ASSY LH / RH	Broken	560.00 F	*560.00 F
11	2		*HEADLAMP BRACKET LH / RH	Not Necessary	20.00 F	*- F
12	1		*BONNET	Dented	200.00 F	*200.00 F
13	1		*BONNET LOCK	Not Necessary	40.00 F	*- F
14	2		*BONNET HINGE LH / RH	Not Necessary	60.00 F	*- F
15	1		*BONNET LOGO	Necessary	45.00 F	*45.00 F
16	2		*FRONT CORNER PANEL LH / RH	Not Necessary	130.00 F	*- F
17	1		*BRACE PANEL	Not Necessary	25.00 F	*- F
18	1		*FRONT SUPPORT PANEL	Dented	150.00 F	*150.00 F
19	1		*FRONT REINF BRACKET LH / RH	N/S Dented	150.00 F	*75.00 F
20	2		*TOW COVER	Crushed	30.00 F	*30.00 F
21	1		*AIR CLEANER ASSY	Broken	250.00 F	*250.00 F
22	1		*AIR INTAKE DUCT	Not Necessary	65.00 F	*- F
23	2		*HARNESS ASSY, WIRING CASING LH / RH	Not Necessary	70.00 F	*- F
24	1		*WASHER TANK	Crushed	80.00 F	*80.00 F
25	1		*RADIATOR SPARE TANK	Broken	140.00 F	*140.00 F
26	1		*RADIATOR	Dented	550.00 F	*550.00 F
27	1		*CONDENSER	Dented	450.00 F	*450.00 F
28	1		*A/C DISCHARGE HOSE	Bent	180.00 F	*180.00 F
29	1		*A/C SUCTION HOSE	Bent	250.00 F	*250.00 F
30	1		*A/C LIQUID PIPE	Not Necessary	220.00 F	*- F
31	1		*CONDENSER FAN BLADE	Not Necessary	65.00 F	*- F
32	1		*RADIATOR FAN BLADE	Not Necessary	65.00 F	*- F
33	1		*INTERCOOLER	Dented	500.00 F	*500.00 F
34	2		*INTERCOOLER AIR GUIDE	Not Necessary	110.00 F	*- F
35	1		*RADIATOR FAN COWLING	Broken	150.00 F	*150.00 F
36	1		*HEATER / AIR CON UNIT	Not Necessary	1,100.00 F	*- F
37	1		*BLOWER ASSY	Not Necessary	450.00 F	*- F
38	1		*INTERCOOLER BRACKET	Not Necessary	30.00 F	*- F
39	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
40	1		*SET FRONT GRILLE CLIPS	Necessary	50.00 FS	*10.00 FS
41	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*35.00 FS
42	1		*COOLANT	Necessary	50.00 FS	*20.00 FS
43	1		*WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
44	1		*WINDSCREEN INNER SEAL	Not Necessary	30.00 FS	*- FS
45	1		*IU BRACKET	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

12/27/21, 4:40 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Sub Total (S\$)	7,515.00	4,705.00
					+ Margin on L,N Items 10.00/10.00% (S\$)	718.50	461.00
					Total Parts (S\$)	8,233.50	5,166.00
Report was unsubmitted during this print-out.							

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOW FEE	New	70.00	50.00
2	TO CUT & WELD, PANEL BEAT AND TO REPLACE FRONT DAMAGED PARTS	New	1,500.00	700.00
3	TO CHECK AND RECTIFY LIGHTING & WIRING	New	250.00	30.00
4	TO PUTTY AND SPRAY PAINT FRONT BUMPER, BONNET, CORNER PANEL LH / RH, FRONT SUPPORT PANEL AND AFFECTED AREAS	New	1,200.00	600.00
5	TO REMOVE & REFIT RADIATOR, CONDENSER, OTHER MAJOR COMPONENTS, TOP UP A/C GAS	New	150.00	50.00
6	TO REMOVE AND REFIT DASHBOARD, HEATER, BLOWER, & INTERIOR TRIMS TO FACILITATE REPAIR	New	350.00	0.00
7	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS	New	150.00	0.00
Gross Labour Cost (\$\$)			3,670.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >