



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBR 5835G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT VISOR	REUSE	72.00	-
1	SIDE MIRROR RH	CRACKED	86.00	86.00
1	FRONT HANDLE BAR	TO REPAIR SEE LABOUR	122.00	-
2	SET FRONT HANDLE BAR GRIP L/R	CRACKED	98.00	98.00
2	SET FRONT HANDLE BALANCER L/R	CUT	88.00	88.00
2	HAND BRAKE LEVER L/R	BENT	62.00	62.00
1	FRONT HANDLE COVER INNER	CRACKED	78.00	78.00
1	FRONT HANDLE COVER UPPER	CRACKED	48.00	48.00
1	FRONT COVER	TO REPAIR SEE LABOUR	28.00	-
1	FRONT HEAD LAMP ASSY	TO REPAIR SEE LABOUR	332.00	-
1	FRONT FENDER (FRONT & REAR)	CRACKED	62.00	62.00
1	FRONT FORK ASSY	TO REPAIR SEE LABOUR	422.00	-
1	FRONT WHEEL	TO REPAIR SEE LABOUR	224.00	-
1	FRONT WHEEL SHAFT	BENT	48.00	48.00
2	FRONT SIDE COWLING L/R	CRACKED	282.00	282.00
2	FRONT SIDE COWLING 'LOGO' STICKER L/R	NECESSARY	24.00	24.00
2	FRONT SIDE SIGNAL LAMP L/R	TO REPAIR SEE LABOUR	72.00	-
2	STEP BOARD GARNISH L/R	CRACKED	78.00	78.00
2	STEP BOARD UNDER COVER L/R	CRACKED	72.00	72.00
1	REAR RH BODY COWLING	CUT	112.00	112.00
1	REAR RH FOOTREST	CUT	45.00	45.00
1	REAR MUFFLER PROTECTOR	CRACKED	108.00	108.00
1	REAR MUFFLER COMPLETE	TO REPAIR SEE LABOUR	422.00	-
	LESS 10% DISCOUNT		-298.50	-129.10
			2,686.50	1,161.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT SIDE COWLING 'LOGO' STICKER L/R (SN)	NECESSARY	80.00	80.00
			80.00	80.00
	<u>LABOUR</u>			
	TOWING CHARGE.		50.00	50.00
	CHECK WIRING SYSTEM AND LIGHT.		80.00	30.00
	WHEEL ALIGNMENT.		100.00	30.00
	FORK ALIGNMENT.		100.00	80.00
	SPRAY PAINTING.		600.00	400.00
	LABOUR FOR REPAIR AND REPLACE PARTS. INCLUSIVE OF THE REPAIR OF FRONT HANDLE BAR, FRONT COVER, FRONT HEAD LAMP ASSY, FRONT FORK ASSY, FRONT WHEEL, FRONT SIDE SIGNAL LAMP L/R AND REAR MUFFLER COMPLETE.		900.00	600.00
			1,830.00	1,190.00
GRAND TOTAL			4,596.50	2,431.90
RECOMMENDED COST OF REPAIR SUM				2,400.00

Report Ref No. CS3/ASM21007873/T1qy3e2-1

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.