

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/III21009855/VTF3E2-1
Date: 18/11/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447
Claimant Vehicle No : SJV9992T **Insured Vehicle No :** SLW2548K
Date of Loss: 11/09/2021 Nature of Claim: TP Claim No: MFL2021D0003950

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJV9992T**
Make & Model: BMW 318I, 1.5 SEDAN LED NAV (A) Engine No: G1911194B38B15A
Reg. Date: 25/08/2015 (Man. Year: 2015) Chassis No: WBA8E32070K497570
Colour: White Odometer: 84687 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,439.60	1,982.65	456.95	18.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	830.00	1,110.00	57.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,379.60	2,812.65	1,566.95	35.78
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	4,379.60	2,250.00	2,129.60	48.63

INSPECTION

Date of Assignment: 08/11/2021
Date Inspected: 12/10/2021 Inspected At: Sheng Li Lai (KAKI BUKIT)
NO. 2 KAKI BUKIT AVE 2, # 01-36 AUTOHUB
KAKI BUKIT
Singapore 417921
Estimated Period of Repair: 3.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2021)
Parts: 143	BMW 318I 1.5 SEDAN LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJV9992T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,194.70 F	*1,194.70 FL
2	1		*REAR BUMPER REINFORCEMENT	Buckled	592.60 F	*485.00 FL
3	1		*REAR BUMPER L/H SIDE RETAINER	Cut	127.30 F	*127.30 FL
4	1		*REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
5	1		*REVERSE SENSOR (2PCS)	Not Working (1Pc Only)	490.00 F	*245.00 FL
6	1		*REAR END PANEL (NPA)	Repair	0.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,439.60	2,087.00
- List Item Discount on L Items 0.00/5.00% (S\$)	0.00	104.35
Total Parts (S\$)	2,439.60	1,982.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,000.00	400.00
2	TO REMOVE AND REINSTALL REVERSE SENSOR	New	140.00	30.00
3	TO PUTTY & SPRAY-PAINT OF AFFECTED AREAS	New	800.00	400.00
			Gross Labour Cost (\$)	830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >