



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T

To: David Gao Hui
c/o 2 Kaki Bukit Ave 2
#01-36, Kaki Bukit Autohub
Singapore 417921

INVOICE

PARTICULARS

AMOUNT

Registration No. : SJV 9992T
Date of accident : 11 September 2021
Make / Model : BMW 318i Sedan LED NAV
Invoice No. : 10046

Being work done and services rendered as follows:

- ✓ Inspection of Vehicle
- ✓ Re-Inspection
- ✓ Appraisal Report
- ✓ 20 Colored Photographs
- ✓ Transport Charges

SGD 440.00

TOTAL SGD 440.00

Dollars: Four Hundred and Forty Only

(Cheque should be crossed and make payable to " TY5 CONSULTANCY ")

TY5 CONSULTANCY



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services: Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T

To: David Gao Hui
c/o 2 Kaki Bukit Ave 2
#01-36, Kaki Bukit Autohub
Singapore 417921

VEHICLE INSPECTION REPORT

Name of Workshop : Sheng Li Lai
Place of inspection : 2 Kaki Bukit Ave 2 #01-36, Kaki Bukit Autohub, Singapore 417921
Date of Accident : 11 September 2021
Date of Inspection : 11 October 2021

VEHICLE PARTICULAR

Registration No.	: SJV 9992T	Chassis Frame No.	: WBA8E32070K497570
Make / Model	: BMW 318i Sedan LED NAV	Engine No.	: G1911194B38B15A
Year of Registration	: 2015	Odometer Reading	: 84,687 KM
Class / Type	: Saloon	Colour	: White

VEHICLE CONDITION

General Condition	: Very Good	Steering	: Serviceable
Paintwork	: Very Good	Foot/ Parking Brake	: Serviceable

TYRE CONDITION

	<u>Size</u>	<u>Thread Balance</u>
Front L/H :	PIRELLI 225 / 50 R17	8mm
Front R/H :	PIRELLI 225 / 50 R17	8mm
Rear L/H :	PIRELLI 225 / 50 R17	8mm
Rear R/H :	PIRELLI 225 / 50 R17	8mm

* The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

	Repairer S\$	Adjuster S\$
Parts	\$ 2,439.60	\$ 2,317.62
Labour	\$ 1,940.00	\$ 1,500.00
	<u>\$ 4,379.60</u>	<u>\$ 3,817.62</u>

TY5 Recommendation

Lump Sum Repair :
\$ 3,050.00

Estimated Repair Duration :

4

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
<u>LIST ITEMS:-</u>					
1	1 pc	rear bumper	deformed	\$ 1,194.70	\$ 1,194.70
2	1 pc	rear bumper reinforcement	buckled	\$ 592.60	\$ 592.60
3	1 pc	rear bumper l/h side retainer	broken	\$ 127.30	\$ 127.30
4	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00
5	2 pcs	reverse sensor @\$245.00	not working	\$ 490.00	\$ 490.00
6	1 pc	rear end panel	dented	repair	repair
				\$ 2,439.60	\$ 2,439.60
		Less	5%		\$ 121.98
				\$ 2,439.60	\$ 2,317.62

Total \$ 2,439.60 \$ 2,317.62



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
		B/F		\$ 2,439.60	\$ 2,317.62
7		To panel beat and renewal of all necessary damaged body parts		\$ 1,000.00	\$ 800.00
8		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00
9		To putty and spray-paint of affected areas		\$ 800.00	\$ 600.00
				<hr/>	<hr/>
				\$ 1,940.00	\$ 1,500.00

Total

\$ 4,379.60 **\$ 3,817.62**



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*


Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact of the collision was delivered Squarely to the LH Rear portion of the vehicle.



(Please refer to the list and survey photographs as attached for more information)

ASSESSMENT RECOMMENDATIONS

COST OF REPAIR

	Repaierer S\$	Adjuster S\$
Parts	\$ 2,439.60	\$ 2,317.62
Labour	\$ 1,940.00	\$ 1,500.00
	<u>\$ 4,379.60</u>	<u>\$ 3,817.62</u>

TY5 Recommendation

Contract Lump Sum of	\$	3,050.00
Estimated Repair Duration :	4	working days (excluding Sat, Sun & Public Holidays)
Enclosed No. Of Photograph :	20	(at the time of static inspection)

Our attached assessment schedule has been checked throughly by us against the actual damages sustained on the vehicle, and we recommend the replacement of parts and repair accordingly. We have adjusted the cost and the repaierer has agreed to undertake the repair at the recommended sum to a acceptable quality and standards. We have not given authorization and instruction to the repaierer to proceed with the repairs.

The survey was done on a **Without Prejudice Basis** and we are reverting the matter to you for a decision.

We thank you for engaging our services and we enclosed herewith our invoice no. 10046

TY5 CONSULTANCY

TERRENCE HONG
AUTOMOTIVE SURVEYOR

NOTE : *This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company via email only and follow up with a phone call, within Fourteen (14) days from the date hereof. Otherwise this revised amount shall be treated as valid.*





