

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG21011349/AYA3Q2**Date:** 12/03/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210065100
Claimant Vehicle No :	SMY6754H	Insured Vehicle No :	GBL4003D
Date of Loss:	06/11/2021	Nature of Claim:	TP
		Claim No:	0730366842SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY6754H		
Make & Model:	BMW 218i, 1.5 (A)	Engine No:	HIDDEN
Reg. Date:	19/03/2021 (Man. Year: 2021)	Chassis No:	WBA12AK0507H60093
Colour:	Green	Odometer:	13764 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,614.06	3,426.69	7,187.37	67.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	980.00	3,140.00	76.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,734.06	4,406.69	10,327.37	70.09
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	14,734.06	3,500.00	11,234.06	76.25
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,907.45		

INSPECTION

Date of Assignment:	08/11/2021	
Date Inspected:	08/11/2021	Inspected At: Kt Motorwerk (HQ) Blk 3012 Bedok Industrial Park E, #01-2020 Singapore 489978
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Ezlyna*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	1,245.80 FL	*1,245.80 FL
2	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	228.70 FL	*- FL
3	1		*FRONT BUMPER BRACKET LH	Not Necessary	235.80 FL	*- FL
4	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	425.80 FL	*- FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	285.90 FL	*- FL
6	1		*FRONT BUMPER FOGLAMP	Not Necessary	570.80 FL	*- FL
7	1		*FRONT BUMPER FOGLAMP COVER	Not Necessary	198.50 FL	*- FL
8	1		*FRONT BUMPER SENSOR	Not Necessary	265.20 FL	*- FL
9	1		*FRONT BUMPER SENSOR HOLDER	Not Necessary	45.60 FL	*- FL
10	1		*FRONT BUMPER LOWER SUPPORT BEAM	Not Necessary	345.60 FL	*- FL
11	1		*FRONT BUMPER GRILLE	Not Necessary	228.70 FL	*- FL
12	1		*FRONT FENDER	Repair	728.30 FL	*- FL
13	1		*FRONT FENDER INNER COWLING	Not Necessary	198.60 FL	*- FL
14	1		*FRONT HEADLAMP	Cracked	2,528.30 FL	*2,528.30 FL
15	1		*FRONT HEADLAMP LOWER BRACKET	Not Necessary	198.70 FL	*- FL
16	1		*FRONT RIM	Not Necessary	987.60 FL	*- FL
17	1		*FRONT BONNET	Not Necessary	1,987.60 FL	*- FL
18	1		*FRONT BONNET LOCK	Not Necessary	387.90 FL	*- FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
20	1		*SET FRONT FENDER INNER COWLING CLIPS	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,723.40	3,804.10
- List Item Discount on L Items 10.00/10.00% (S\$)	1,109.34	377.41
Total Parts (S\$)	10,614.06	3,426.69

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	400.00
2	SPRAY PAINTING -PEARL	New	1,800.00	500.00
3	CHECK WIRING ON HEADLAMP AND FOCUSING	New	180.00	30.00
4	ANTI RUST	New	100.00	0.00
5	REMOVE AND INSTALL FRONT SENSOR	New	120.00	50.00
6	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			4,120.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >