

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011350/AGQF3E2

**Date:** 12/05/2022

### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001219705		
<b>Claimant Vehicle No :</b>	SMQ9386J	<b>Insured Vehicle No :</b>	SFV3434A		
Date of Loss:	02/11/2021	Nature of Claim:	TP	Claim No:	264952

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ9386J	Engine No:	L15B72452362
Make & Model:	HONDA CIVIC, 1.5 TURBO VTI-S SR (A)	Chassis No:	MRHFC1660HT000144
Reg. Date:	06/06/2017 (Man. Year: 2017)	Odometer:	150062 km
Colour:	Blue		
Engine Capacity:	1498 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,454.40	1,288.48	1,165.92	47.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	580.00	1,270.00	68.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,304.40</b>	<b>1,868.48</b>	<b>2,435.92</b>	<b>56.59</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,304.40</b>	<b>1,250.00</b>	<b>3,054.40</b>	<b>70.96</b>

### INSPECTION

Date of Assignment:	08/11/2021	Advance Auto Garage (HQ)
Date Inspected:	09/11/2021 Inspected At:	23 KAKI BUKIT AVENUE 4 #04-01 AAS KAKI BUKIT CENTRE
Estimated Period of Repair:	2.0 days	Singapore 415933

**Adjuster:** XING GUO QIANG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
<b>Parts:</b>	143	HONDA CIVIC 1.5 TURBO VTI-S SR (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMQ9386J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	617.20 F	*617.20 FL
2	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
3	1		*REAR BUMPER SIDE HOLDER LH	Not Necessary	35.00 F	*- FL
4	1		*REAR BUMPER TOW COVER	Not Necessary	32.10 F	*- FL
5	1		*REAR BUMPER LOWER GARNISH	Cracked	268.20 F	*268.20 FL
6	1		*REAR BUMPER SIDE GRILLE LH	Cracked	73.50 F	*73.50 FL
7	1		*REAR BUMPER REINFORCEMENT	Dented	246.40 F	*246.40 FL
8	1		*REAR BUMPER REFLECTOR LH	Not Necessary	45.40 F	*- FL
9	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS
10	1		*REAR END PANEL	Not Necessary	398.80 F	*- FL
11	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
12	1		*TAILLAMP LH	Cut	367.80 F	*367.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,454.40</b>	<b>1,603.10</b>
<b>- List Item Discount on L Items 0.00/20.00% (S\$)</b>	0.00	314.62
<b>Total Parts (S\$)</b>	<b>2,454.40</b>	<b>1,288.48</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	800.00	250.00
2	SPRAY PAINTING	New	600.00	250.00
3	WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
6	TO SPRAY TUFF COAT	New	150.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,850.00</b>	<b>580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >