

TP MS16.
Xiao Chun.

SMW 9386J. 2017 June
Honda Civic 1498cc
MRHFC1660HT000/44.

Rear Bumper	Deformed	617.20	✓
Rear Bumper Lips.	NH	30(SN)	✓
Rear Bumper Side Holder LH.	NH RH	35	✗
Rear Bumper Tow Cover	NH RH	32.10	✗
Rear Bumper lower Gracush.	Cracked	268.20	✓
Rear Bumper Side Grille LH.	Cracked	73.50	✓
Rear Bumper Reinforcement.	Dented	246.40	✓
Rear Bumper Side Reflector LH.	NH RH	45.40	✗
Reverse Sensor	NH RH	280(SN)	✗
Rear End Panel	2 NH RH	398.80	✗
Rear End Panel Sealant	NH RH	60(SN)	✗
Tail Lamp LH.	Cut	367.80	✓

1205.30

964.24

S.N. 30

SMQ9386J.

Panel Beating
Spray Painting.
Wiring.

580

~~800~~ 250

~~600~~ 250

~~50~~ 30

~~100~~ 50

150 X

150 X

To remove cruise sensor
To remove upholstery.
To spray tuft coat.

total: 1574.24

H/S: 1250.

02 days.

1.710

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: